

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 20/09/2021

User ID

: JeongCH

	Section A - Accident Details
Registration Number	SG6173H
Case Reference Number	BUS/09/21/1006
Registration Date	3/20/2020
Company Type	SMRT Buses Ltd
/lake	MAN
Model	A95 MAN E6
lame of Driver	Hao Lei
ype of Accident	Open Door Case
ccident Date and Time	9/14/2021 8:40 AM
ccident Reported Date and Time	9/17/2021 2:52 PM
Surveyor Required?	No
urvey by	
ehicle is Towed Back?	No
owed Back Date and Time	
eplacement Vehicle issued?	No
bb Card Number	F7 3553
pecial Instruction to ARC,if any	SG6173H-LEFT FRONT PORTION AND FRONT LEFT BUMPER DENTED AND CRACKED SLX2476D (TP) INSURED WITH CHINA TAIPING
repared Date and Time	9/20/2021 1:59 PM
nassis Number	WMAA95ZZXKF009722
leage	
ork Shop	The state of the s
pair Completion Date and Time	

A STATE OF THE PARTY OF THE PAR	Section B - Summary of Repair Estimates				
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
otal Labour Cost	\$795.00	\$0.00			
otal Spray Cost	\$602.00	\$0.00			
otal Spare Part Cost	\$300.00	\$0.00			
otal Other Cost	\$0.00	\$0.00			
OTAL COST	\$1,697.00	\$0.00			
ump Sum Total	\$0.00	\$0.00			
umber of Repair Days	3.0	8 P 2 1			
epared / Adjusted By	ARC Manager Team				
RC / Surveyor Sign Off Date	20/09/2021 2:07 PM				
gnature	8	×			
marks					

Secti	on C - Quotation and Accident Invoice Details	TAXABLE OF THE
tuotation Number	Invoice Number	Constitute The Table
tuotation Date	Invoice Date	
voice Amount	Prepared Date	



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 75770

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 20/09/2021

User ID : JeongCH

	The state of the s		Secti	on D - Deta	ils of Repair E	stimates		Control of Control	Salar Carlotte Balling
art 1 - Labo	ur Works	10 St = 20 St		, State				- Charles	
ob scope			Quotation from AR \$795.00				Adjusted by Surveyor, if applicable		
							530		
			\$795.00					100 March 25 Mar ( 2	
art 2 - Spra	y Painting & I	Panel Beating Rela	ted Works		10 V 1 V 1 V 1 V 1		n parties of the second		
			Quotation from ARC				Adjusted by Surveyor, if applicable		
ROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$602.00				432		
otal Spray Pa	ainting & Panel	Beating		\$602.00					
art 3 - Other	Costs - Acci	dent and Acciden	Repair Related Expens	se	A SAME AS A SAME OF	Mark Street			
ab Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
otal Other Co	sts	2004W29 L. 2004 28. 10. 10. 10.	Service and the service service and the	deposit di S. R. 1942	ASSESSED AND AND AND AND AND AND AND AND AND AN	Control son		1	
art 4 - Spare	Parts / Mate	rial Usage			CAREE NAME OF STREET		11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		S. S
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approve	ed Surveyor Approved
13917	9		TRIM, WHEELARCH: FOR MAN A95 EURO 6	1.00	\$250.00	10.00	\$225.00	Replace	CM
li li	1 14/2		SMRT STICKER	1.00	\$75.00	0.00	\$75.00	Replace	m
otal	A STANFOLD	1 7 1		P P	\$325.00	the part of the	\$300.00	1 1 1 1	

List Price \$

Discount (%) Final Price (\$) ARC Check

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Quantity

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Stock Number Part Name

Respective Plans Print Respective Plans

Surveyor Check

art Number

otal

Portion