



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JEREMY GOH		Ref: CS3/AIG21000491/T1tf3e2-1 Date: 12/10/2021 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJA 3531R	Veh. Inspected	SMS 6992T
Policy No.	2100238096	Coverage (\$)	0.00
Claim No.	0367656983SG	Excess (\$)	0.00
Assign From	JEREMY GOH	Assign Date	22/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA FIT	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GK33415867	Colour	BLUE
Odometer	11826 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	10/01/2021	Inspection Date	12/01/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	