

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM21009897/Bvce2		
	8 SHENTON WAY SINGAPORE 0688		Date:	08/12/2021		
	ATTN: PAY DANIE	L		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 291R	Veh. Inspected	ł	SCR 989S	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S1M03IH8	Excess (\$)		0.00	
	Assign From	PAY DANIEL	Assign Date		22/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ C180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WDD2050402F049125	Colour		SILVER	
	Odometer	89685 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/50 R17	CONTINENTAL		6 mm	
	L/H Front Tyre	225/50 R17	CONTINENTAL		6 mm	
	R/H Rear Tyre	225/50 R17	CONTINENTAL		6 mm	
	L/H Rear Tyre	225/50 R17	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5. General Information						
	Accident Date	21/09/2021	Inspect Date /	Time	23/09/2021 ( 03:23 PM )	
	Survey held at	Survey held at MERLIN MOTOR & ENGINEERING WORKS  BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-13 AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		7 Worki	ing Days	

Report Ref No. CS3/ASM21009897/Bvce2

Inspected By

LIM TEOW GUAN

M

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser