

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH 9180L

Date: 18/09/2021

Make : HYUNDAI

Insurance: CHINA TAIPING

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER BRACKET TOP LH			\$44.80
1	FRT FENDER LH			\$663.00
1	HEADLAMP LH			\$1,800.00
	SUB TOTAL			\$3,582.00
	LESS 20%			\$716.40
	DISCOUNTED TOTAL			\$2,865.60
	FRT FENDER ADVERTISEMENT LOGO LH			\$100.00
				\$100.00
	Labour Charge			
	PANEL BEATING			\$600.00
	SPRAY PAINTING CHARGE			\$600.00
	CHECK ALL LIGHTING			\$60.00
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL			\$4,225.60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan @ LKK Auto Ins  
 82235769  
 20/9/21 16:45  
 3 days up  
 L/S after repair photos

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 18.09.2021 08:24 Page : 1

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 4119108

JC NO305487347

CUSTOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SH 9180L	MILEAGE
MR/MS	7010045	MAKE: HYUNDAI	FUEL
CUSTOMER NO.	383 SIN MING DRIVE	MODEL: I-40	E..... 1/2.....
ADDRESS	Singapore SINGAPORE 575717	DATE/TIME IN	17.09.2021 16:05
TEL (R)	65508755	YR OF MANU.	TARGET DATE
(P)	(O)	09.06.2016	
DISCOUNT CARD NO.		CHASSIS CODE KMHLB41UMGU090127	COMPLETION DATE/TIME

### JOB DESCRIPTION


Accident Date: 17.09.2021

NATURE: 3P 17.09.2021

S / NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

e:

0.:

File No.:

SH 9180L

YY

Vehicle No.:

SH 9180L

of Service Advisor

Signature/Date

Name of Service Advisor

Date \_\_\_\_\_

returned to Service Reception upon collection

To be kept by Security Guard