

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CC3/GRB 21009958/R1BS3

1401

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SOP 9888P

at Workshop m/s PERFORMANCE

of 303, ALANZA RD

Insured: GRB

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 125K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SOP 9888P Yr Regn: 2020 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 216I GRAN TOURER c.c 1499

Colour: BLACK A/C: Insured / Std / NI / NA

Sp.Reading: 27277 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA6V120305R45474

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 09/09/21 D.O.I. 27/09/21

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 64K

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2)

Add Fee: : Site Insp (\$) _____ S + RS, _____ SI

: Interview (\$) Photos

: Tech. Invs (\$) Others

: Weekend (\$)

Report Format : _____

Lump Sum / I.B.I.: (\$) _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1401
Vehicle No.:	SDP9888P
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2021
Vehicle Make:	BMW
Vehicle Model:	216i GRAN TOURER
Primary Colour:	Black
Manufacturing Year:	2020
Engine No.:	36635981B38A15A
Chassis No.:	WBA6V120305R45474
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$32,606.00
Original Registration Date:	25 Aug 2020
First Registration Date:	25 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$37,649.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2030
PARF Rebate Amount:	\$28,236.00
COE Expiry Date:	24 Aug 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,710.00
COE Rebate Amount:	\$31,803.00
Total Rebate Amount:	\$60,039.00

The information contained herein is correct as at 28 Sep 2021

OK

BMW 2 Series 216i Gran Tourer

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

Price	\$125,800		
Depreciation ⓘ	\$11,990 /yr View models with similar depre	Reg Date	27-Aug-2020 (8yrs 10mths 29days COE left)
Mileage	24,000 km (22.1k /yr)	Manufactured ⓘ	2020
Road Tax ⓘ	\$684 /yr	Transmission	Auto
Dereg Value ⓘ	\$60,196 as of today (change)	OMV ⓘ	\$32,724
COE ⓘ	\$35,710	ARF ⓘ	\$37,814
Engine Cap	1,499 cc	Power	80.0 kW (107 bhp)
Curb Weight ⓘ	1,490 kg	No. of Owners ⓘ	1
Type of Vehicle	MPV		