

Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : <b>b1 59474</b> Date Estimated : <b>10/09/2021</b> Prepared By : <b>Foong Shiuh Jye</b>	Page No. : <b>1 of 5</b>
--	--------------------------

<b>- ESTIMATE REPAIR FOR -</b> Wong Yik Pern Reuben 8 College Avenue East #05-61  Singapore 138615	<b>- ACCOUNT - 219</b> India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9888P	WBA6V120305R45474	25/08/2020	216i Gran Tourer	23514

DESCRIPTION	VALUE
To replace rear bumper, boot lid including to knock out dented area caused by the accident	<del>1700</del> 2,550.00
To respray rear bumper and boot lid	<del>1826</del> 1,923.00
To carry out body cavity preservation. (Per panel).	<del>112</del> 118.00
To remove and install rear windscreen glass to facilitate repair.	<del>574.00</del>
To conduct water leak tests.	<del>75.00</del>
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	<del>504</del> 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	<del>168</del> 177.00
To check electrical wiring system and lighting at the rear section for proper function.	<del>168</del> 177.00
Sundries.	<del>?</del> 150.00
<b>Total Labour 1:</b>	<b>6,275.00</b>

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <i>LI</i>	1	1,216.40	1,216.40
RR BUMPER LH SIDE GUIDE <i>?</i>	1	161.15	161.15
# REAR BUMPER CARRIER <i>?</i>	1	483.40	483.40
# RR BUMPER LH INNER SIDE GUID <i>?</i>	1	161.15	161.15
# REAR BUMPER TRIM STRIP (BLAC <i>LI</i> )	1	72.20	72.20
# REAR BUMPER PANEL PRIMED (LI <i>LI</i> )	1	1,050.65	1,050.65

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : **b1 59474**  
Date Estimated : **10/09/2021**  
Prepared By : **Foong Shiuh Jye**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDP9888P	WBA6V120305R45474	25/08/2020	216i Gran Tourer	23514

DESCRIPTION	QTY	PRIC	VALUE
# LETTERING 216 <i>per</i>	1	64.75	64.75
GROMMET <i>per</i>	2	0.80	1.60
PLAQUE 74MM <i>per</i>	1	71.95	71.95
REAR WINDOW (ESG) ? <i>photo</i>	1	657.60	657.60
HOOK AND LOOP FASTENER ?	6	2.20	13.20
REAR LH REFLECTOR ?	1	39.05	39.05
REAR LH LIGHT IN THE SIDE PANEL X	1	376.30	376.30
(DG) CLEANER R1 (100ML) <i>per</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>per</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>per</i>	1	27.85	27.85

Total Parts : **4,686.50**

**Claims OD / 3rd Party / Uninsured losses / Direct Settlement**

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&Time 27/09/21 @ 1026 Excess S\$ \_\_\_\_\_

Surveyor's Name Rxall Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

**RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No**

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,275.00
Parts	:	4,686.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	767.31
<b>Grand Total</b>	:	<b>11,728.81</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE...