

ASS. REC. BY:

REF:

C12/ 210100001ku

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: SLM 6761L

at Workshop m/s

Estum

of

Insured:

GBH 2682C

Policy No.

DMCVSNA00034622103

Claims No.

SNM21D205433

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4 days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM 67612

Yr Regn:

04, 17

Type: M.C.P. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 6

c.c.

2488

Colour

m. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

104 712

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM 6 GL 1031140120220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45ZR19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

23/9/21

D.O.I.

22/9/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed L/S \$6400, 4 repair days.

(RED \$12019.20; 65%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 25/11 TYPIST

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

TP

ump Sum H.B. (\$

6400

Chong Pong



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005488N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Bin Ming Drive
Singapore 675718
(T) 6753 2112 (F) 6461 0394

WORKSHOP
176 Bin Ming Drive
Bin Ming Auto Care #01-14, #01-15, #01-16
Singapore 675721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SLM 6761 L

Parts	(a) Cost / List Price Items	\$	18,474.00
	Plus/Less 20%	\$	3,694.80
	Total of Cost / List	\$	14,779.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	450.00
Total Parts Cost		\$	15,229.20
Labour		\$	3,190.00
Total		\$	18,419.20

Not Authorised
C/Pm &
Heavy After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Le

Date:

27/9/21



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SLM 6761 L**
Make & Model : **MAZDA 6**
Chassis No. : **JM6GL1031H0120220**

Submit By : **Carmen Lim**
Year Manufacture : **2017 Apr**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Bonnet <i>R</i>	1	\$1,285.00		X
2	Bonnet lock <i>R</i>	1	\$269.00		X
3	Bonnet hinge LH <i>R</i>	1	\$67.00		X
4	Bonnet hinge RH <i>R</i>	1	\$67.00		X
5	Headlamp RH <i>CM</i>	1	\$4,975.00		✓
6	Front grille	1	\$161.00		?
7	Front grille logo	1	\$86.00		?
8	Front grille chrome <i>Sn</i>	1	\$195.00		X
9	Front support panel (complete)	1	\$594.00		?
10	Front bumper <i>Br/Tn</i>	1	\$1,312.00		✓
11	Front bumper clip <i>mm</i>	10	\$50.00		✓
12	Front bumper reinforcement <i>R</i>	1	\$680.00		X
13	Front bumper side retainer LH <i>Sn</i>	1	\$35.00		X
14	Front bumper side retainer RH <i>CM</i>	1	\$35.00		✓
15	Front bumper bracket LH <i>R</i>	1	\$48.00		X
16	Front bumper bracket RH <i>R</i>	1	\$48.00		X
17	Front bumper sponge <i>Sn</i>	1	\$97.00		X
18	Front bumper chrome moulding RH <i>nd</i>	1	\$112.00		✓
19	Fog lamp RH	1	\$694.00		?
20	Fog lamp garnish RH	1	\$53.00		?
21	Front bumper sensor	2	\$254.00		?
22	Front bumper lower rubber <i>Sn</i>	1	\$176.00		X
23	RH front fender <i>Br</i>	1	\$394.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLM 6761 L**
 Make & Model : **MAZDA 6**
 Chassis No : **JM6GL1031H0120220**

Submit By : **Carmen Lim**
 Year Manufacture : **2017 Apr**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front fender undershield <i>Dis</i>	1	\$165.00		✓
25	RH front fender undershield clip <i>Mc</i>	10	\$50.00		✓
26	RH front lower arm	1	\$554.00		X
27	RH front shock absorber	1	\$393.00		X
28	RH front shock absorber top mouting	1	\$107.00		X
29	RH front shock absorber stopper	1	\$65.00		X
30	RH front knuckle arm	1	\$448.00		X
31	RH front knuckle bearing	1	\$597.00		X
32	RH front wheel hub	1			.
33	RH front wheel hub lock nut	1	\$35.00		X
34	RH front tie rod	1	\$165.00		X
35	RH front tie rod end	1	\$185.00		X
36	RH front drive shaft	1	\$2,525.00		X
37	RH front rim	1	\$1,498.00		X
38	RH front tyre	1	\$450.00	S.N	X
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14 , #01-15 , #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SLM 6761 L**
Make & Model : **MAZDA 6**

Submit By : **Carmen Lim**
Year of Manufacture : **2017 Apr**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,SUPPORT PANEL, RHF FENDER,RHF DOOR)	\$1,200.00	300
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,SUPPORT PANEL, RHF FENDER,RHF DOOR)	\$1,000.00	600
3	To check wiring	\$50.00	20
4	To remove & refit front bumper sensor	\$120.00	50
5	To tuff coat	\$150.00	30
6	To remove & refit aircon condensor to assist work load,to top up A/C gas. <i>nn</i>	\$150.00	X
7	To remove & refit radiator to assist work load. <i>nn</i>	\$150.00	X
8	To remove & refit undercarriage to assist work load. <i>nn</i>	\$250.00	X
9	To do wheel alignment. <i>nn</i>	\$120.00	60

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/09/2021 09:05 (SGT)
Date of Accident	23/09/2021 13:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	GEYLANG LOR 25A CAR PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM6761L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LEE KUAN YANG
NRIC No	SXXXX674G
Email Address	bryan@ntagency.com
Mobile Phone No	(Phone) +65-97107733
Alternative Phone No	+65-97107733

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2488

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA539425
Cover Note Number	-

DRIVER

Name of Driver	LOH CHUN HOOI
Passport No/FIN	GXXXX619U

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time 23-09-2021 @ 15:45

Driver's Signature (If driver is not the policyholder) / Date & Time 23-09-2021 @ 15:45

Witnessed by Reporting Centre Personnel

Sketch Plan

