



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM21010007/Avce2 Date: 25/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8737E	Veh. Inspected	SLF 8388E	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S1M03IRR	Excess (\$)	0.00	
Assign From	LOH CYNTHIA	Assign Date	27/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11114719	Colour	WHITE	
Odometer	136615 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	6 mm	
L/H Front Tyre	215/60 R16	FALKEN	6 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/09/2021	Inspection Date	28/09/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	