

KURU & CO

Advocates & Solicitors

UEN No. 53130937A / GST Registration No: M90366606R

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727

Tel: 65322 009 (5 lines) / Fax: 65322 007 (Our fax no. is not for service of court documents)

Our ref: L.21.0627.oly

27 September 2021

BY CERTIFICATE OF POSTING

Daimler Fleet Management Singapore Pte Ltd
1 Gateway Drive
#15-08 Westgate Tower
Singapore 608531

(Yr ref: XE 4566Y)

BY EMAIL ONLY

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

(Yr ref: XE 4566Y)

Dear Sirs,

**ACCIDENT INVOLVING SJK 6462J AND XE 4566Y ON 18.08.2021
AT/ALONG HARBOUR DRIVE
INJURED DRIVER: QUEK SOO MENG**

We act for **Quek Soo Meng**, owner of vehicle registration number **SJK 6462J** who was also injured in the above-captioned road traffic accident.

We are instructed to claim for damages against you in connection with the above-captioned road traffic accident involving our client's vehicle and your vehicle registration number **XE 4566Y**.

We are instructed that the accident was caused by your/your driver's/your insured's negligent driving and/or management of your/your insured's vehicle. As a result of the accident, our client has suffered injuries and our client's vehicle was damaged. Our client had been put to loss and expense, particulars of which are as follows:

Cost of repairs	\$13,900.00
Loss of use	\$ 1,120.00
Survey fee	\$ 860.00
LTA fee/s	\$ 7.49
Incidentals (Inclusive of GST)	\$ 53.50
Cost at this stage (Inclusive of GST)	\$ 1,070.00

We shall revert with our client's claim for General Damages and related Special Damages in due course.

Enclosed are the supporting documents for your perusal:

Pre-repair Notification email dated 19 August 2021

15 copies of accident scene photographs

Our client's SAS/police report

Your/your insured's LTA search

Repair Bill

Survey report with **115 colour scanned** photographs

PARF/COE Rebate for **SJK 6462J** from Land Transport Authority

Vehicle registration details of **SJK 6462J** from Land Transport Authority

LTA search Transaction

Our ref: L.21.0627.oly

27 September 2021

**ACCIDENT INVOLVING SJK 6462J AND XE 4566Y ON 18.08.2021
AT/ALONG HARBOUR DRIVE
INJURED DRIVER: QUEK SOO MENG**

We have on 19 August 2021 notified your insurer of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurer on 23 August 2021.

Should you have a counterclaim against our client arising out of the accident, you are required to send us a letter giving full particulars of the counterclaim with all relevant supporting documents within **8 weeks** from your receipt of this letter.

Please also note that you or your insurer should send us an acknowledgement of receipt of this letter within **14 days** of your receipt of this letter, failing which our client will have no alternative but to commence proceedings without further notice to you or your insurer.

Yours faithfully,



Encl.

N.B. Supporting documents are forwarded only to your insurer

Cc. Liberty Insurance Pte Ltd (**Mutual client - SJK 6462J**) / **BY EMAIL ONLY**
Please do not prejudice our mutual client's claim in whatsoever way. Meanwhile, we would be obliged if you could let us have a complete set of third party's SAS/police report if you have received a copy of same for our attention.

Cc. Client

1AIG Our ref: L21.0627.cj // ACCIDENT INVOLVING SJK 6462J & XE 4566Y ON 18/08/21
AT/ALONG HARBOUR DRIVE NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

From: Kuru & Co (kurulegal@yahoo.com.sg)

To: claimsadminsUPPORT@aig.com; claimsdocmanagement@aig.com; norsiah.mdnoor@aig.com

Date: Thursday, 19 August 2021, 05:24 pm SGT

Dear Sirs

**ACCIDENT INVOLVING SJK 6462J & XE 4566Y ON 18/08/21
AT/ALONG HARBOUR DRIVE
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY**

We act for **QUEK SOO MENG**, whose vehicle registration number **SJK 6462J** was damaged in the above accident.

A copy of the Police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727



Tel: 6532 2009

Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.



21 0627 PR.pdf
120.7kB







SINGAPORE POLICE FORCE



T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

1 of 3

Report No. T/20210819/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2021 12:45		Vide Report No.:		Station Diary No.: 9	
Informant's Particulars					
Name of Informant: QUEK SOO MENG			Address: APT BLK 33 BALAM ROAD #07-01 SINGAPORE 370033		
ID Type / ID No.: NRIC NO / S1245834G			Contact No.: Home/Office: Mobile: 96478982		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 10/05/1957	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Senior executive			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/08/2021 13:15	Type of Location: Straight Road
Location: HARBOUR DRIVE				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJK6462J		TOYOTA		Black		0
XE4566Y		MERCEDES BENZ		White		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

2 of 3

Report No. T/20210819/2041

CONTINUATION OF REPORT

Driver			
Name	QUEK SOO MENG	ID No.	S1245834G
Related Vehicle	SJK6462J	Contact No.	96478982
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/08/2021	Date Discharge	19/08/2021
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	ONG ENG JOO	ID No.	F7017326M
Related Vehicle	XE4566Y	Contact No.	96689557
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location. I was driving my vehicle in a two lane road with the another party towards IPAT Building 2, suddenly the truck wanted to change lane and hit the rear side of my car and my car skidded to the right and also hit onto his front right bumper that caused some scratches. My car was badly also damaged and both doors were badly dented. Both of us came out of our vehicles to take photo of the accident and damages. No Ambulance or traffic police was at scene. PSA site has the CCTV footage of the accident, however they do not allow me to view it. At night I felt pain on my right arm and neck, I then decided to go see a doctor today and I received 5 days MC. The doctor also prescribed to me some muscle relaxant pills, pain killers and gastric pills. I am lodging this report for my own record purposes and to claim insurances.



**SINGAPORE
POLICE FORCE**



T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

3 of 3

Report No. T/20210819/2041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
G /
Sgt 1 PHUA JIA JIN, DARREN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI TAY CHUN KEEN
Contact No.: 65476436

Signature Of Informant:

Date/Time:
19/08/2021 12:45

Classification Of Case:

SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/08/2021 16:33 (SGT)
Date of Accident	18/08/2021 13:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	HARBOUR DRIVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK6462J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	QUEK SOO MENG
NRIC No	SXXXX834G
Email Address	SOOMENGQ@GMAIL.COM
Mobile Phone No	(Phone) +65-96478982
Alternative Phone No	(Office) +65-96478982

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SI20V11888/VPE/R01/E00
Cover Note Number	-

DRIVER

Name of Driver	QUEK SOO MENG
NRIC No	SXXXX834G

Date Of Birth	10/05/1957
Occupation	Outdoor
Date Of Driving Pass	20/06/1977
Driving experience	44 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96478982
Alt. Phone Number	(Office) +65-96478982
Email Address	SOOMENGQ@GMAIL.COM
Address	BLK 33 BALAM ROAD
Address complement	#07-01
Postcode	370033
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	MacPherson Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18007449999
Alt. Police Station Phone No	(Fax) +65-65476366
Police Station Address	Blk 54 Pipit Road #01-82/84 Singapore 370054
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT NO T/20210819/2041

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4566Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	QUEK SOO MENG
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	RIGHT ARM AND NECK
Injured person in which vehicle?	SJK6462J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Refer to Police Report No T/20210819/2041

Declaration

We declare the foregoing particulars are true in every respect.

John

W. J. B.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

14/12/21

Witnessed by Reporting Centre
Personnel













































**SINGAPORE
POLICE FORCE**



T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

1 of 3

Report No. T/20210819/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/08/2021 12:45		Vide Report No.:		Station Diary No.: 9
Informant's Particulars				
Name of Informant: QUEK SOO MENG		Address: APT BLK 33 BALAM ROAD #07-01 SINGAPORE 370033		
ID Type / ID No.: NRIC NO / S1245834G		Contact No.: Home/Office: Mobile: 98478982		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 64	Date of Birth: 10/05/1957	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: Senior executive		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/08/2021 13:15	Type of Location: Straight Road
Location: HARBOUR DRIVE				
Weather: Sunny		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SJK6462J		TOYOTA		Black		0
XE4566Y		MERCEDES BENZ		White		0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

2 of 3

Report No: T/20210819/2041

CONTINUATION OF REPORT

Driver			
Name	QUEK SOO MENG	ID No.	S1245834G
Related Vehicle	SJK6462J	Contact No.	96478982
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/08/2021	Date Discharge	19/08/2021
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	ONG ENG JOO	ID No.	F7017328M
Related Vehicle	XE4566Y	Contact No.	96689557
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location. I was driving my vehicle in a two lane road with the another party towards TPAF Building 2, suddenly the truck wanted to change lane and hit the rear side of my car and my car skidded to the right and also hit onto his front right bumper that caused some scratches. My car was badly also damaged and both doors were badly dented. Both of us came out of our vehicles to take photo of the accident and damages. No Ambulance or traffic police was at scene. PSA site has the CCTV footage of the accident, however they do not allow me to view it. At night I felt pain on my right arm and neck, I then decided to go see a doctor today and I received 5 days MC. The doctor also prescribed to me some muscle relaxant pills, pain killers and gastric pills. I am lodging this report for my own record purposes and to claim insurances.


**SINGAPORE
POLICE FORCE**


T/20210819/2041

Police Station Of Origin:
MacPherson NPP
54 Piplt Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

3 of 3

Report No. T/20210819/2041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

G /

Sgt 1 PHUA JIA JIN, DARREN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

19/08/2021 12:45

Officer In Charge Of Case:

TR / AEIT /

SSI TAY CHUN KEEN

Contact No.: 65476436

Classification Of Case:

Authentication Stamp

NP168

Enquire Vehicle Owner Details (As At 18 Aug 2021 / 13:15:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner Name:

**DAIMLER FLEET MANAGEMENT
SINGAPORE PTE. LTD.**

Registered Block/House No.:

1

Registered Unit No.:

15 - 08

Registered Postal Code:

608531

Owner ID:

199803778Z

Registered Address Type:

**Private Residential (Condo Apt or House) /
Shopping / Office Complexes**

Registered Street Name:

GATEWAY DRIVE

Registered Building Name:

WESTGATE TOWER

Vehicle Insurance Details

Vehicle No.:

XE4566Y

Insurance Company Name:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Make Description/Model:

**MERCEDES BENZ / ACTROS 2043S 4X2
3600 M-CAB**

Enquire Vehicle's Insurance Particulars (As At 18 Aug 2021 / 13:15:00)

Vehicle No.:

XE4566Y

Make Description/Model:

**MERCEDES BENZ / ACTROS 2043S 4X2
3600 M-CAB**

Insurance Company Name:

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Business Transaction Reference No.:

20210819171442652600

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

HUAT AUTOMOBILE AIR-CON SERVICE

Blk 3007 Ubi Road 1

#01-404

Singapore 408701

Tel: 6746 1868 Fax: 6746 2065

Final Bill

To

Quek Soo Meng

Bill #

3022

Vehicle No.

SJK6462J

Date

15/09/2021

Description**Amount**

Recommended cost of repair by lump sum as per surveyor's report

\$13,900.00

Ref. PA/MI/21/1017/1 by Perfect Automobile Appraisal Services

Total: **\$13,900.00**

PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080

Hand phone No. 96683949 Fax No. 63880908

Business Registration Nos. 53103119E

INVOICE

To : Quek Soo Meng
c/o : Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

Date : 6th September 2021

Invoice No. : 10301/21

ITEM	PARTICULARS	AMOUNT
	Services rendered for automobile inspection report : Survey fee : (including transport charges and photographs) Veh. No : SJK 6462 J Model : Toyota Altis 1.6 Our Ref : PA/MI/21/1017/1 Dollars : Eight hundred and sixty only.	\$ 860.00

Perfect Automobile Appraisal Services



PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080

Hand phone No. 96683949

Company Registration No. 53103119E

THIRD PARTY CLAIM

To : Quek Soo Meng
c/o : Block 3007 #01-404
Ubi Road 1
Singapore 408701

Date : 6th September 2021

Our Ref : PA/MI/21/1017/1

REFERENCE :

ASSIGNED BY : Owner
ASSIGNED ON : 20th August 2021

WORKSHOP : Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

ACCIDENT DATE : 18th August 2021
SURVEY DATE : 20th August 2021

VEHICLE DETAILS :

REGN PLATE	: SJK 6462 J	COLOUR	: Black
MAKE & MODEL	: Toyota Altis 1.6	GEN BODY WORK	: Good
YEAR REGN	: 2008	AUDIO PLAYER	: Yes
ENG CAPACITY	: 1598cc	AIR CONDITIONER	: Yes
ENGINE NO.	: 3ZZ4804582	STEERING	: Serviceable
CHASSIS NO	: MR053ZEE106121425	HAND BRAKE	: Serviceable
MILEAGE	: 272734Km	FOOT BRAKE	: Serviceable

TYRES SIZE & CONDITION :

FRONT O/S : Pirelli 205/55 R 16 approximately 60%
FRONT N/S : Pirelli 205/55 R 16 approximately 60%
REAR O/S : Pirelli 205/55 R 16 approximately 60%
REAR N/S : Pirelli 205/55 R 16 approximately 60%

Note : The above percentage represent the remaining estimated life of the tyre treads.

Our Ref : PA/MI/21/1017/1

Veh. No. : SJK 6462 J

GENERAL DESCRIPTION OF DAMAGES :

At the time of inspection, we noted that this vehicle sustained damages along the o/s body length.

For more details of the damages, please see schedule and photographs attached.

Attached one hundred & fifteen (115) photographs taken during our inspections.

CONCLUSIONS & RECOMMENDATIONS :

ORIGINAL QUOTATION : \$ 19,407.73

REVISED QUOTATION : \$ 13,900.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately ten (10) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a '**WITHOUT PREJUDICE**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressee's designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

Our Ref : PA/MI/21/1017/1

Veh. No. : SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LIST PARTS

1 pc	Front o/s fender	dented	\$ 642.10	\$ 642.10
1 pc	Front o/s fender 'VVTI' emblem	necessary	\$ 65.20	\$ 65.20
1 pc	Front o/s fender inner shield	distorted	\$ 166.10	\$ 166.10
1 pc	Front o/s fender inner panel	repairable	\$ 455.80	\$ -
1 pc	Front o/s door	dented	\$ 1,271.50	\$ 1,271.50
1 pc	o/s door outer mirror assy	holder snapped	\$ 844.90	\$ 844.90
1 pc	Front o/s door outer protector	dented/ bent	\$ 311.50	\$ 311.50
1 pc	Front o/s door inner lock	dented/ jammed	\$ 603.20	\$ 603.20
1 pc	Front o/s door glass outer moulding	dented/ bent	\$ 141.80	\$ 141.80
1 pc	Front o/s door inner rubber	necessary	\$ 168.20	\$ 168.20
1 pc	Front o/s door inner trim board	holder snapped	\$ 925.40	\$ 925.40
1 pc	Front o/s door glass regulator & motor	dented/ failed	\$ 415.90	\$ 415.90
1 pc	Front o/s door outer handle	bent	\$ 245.10	\$ 245.10
1 pc	Front o/s door outer handle knock	dented	\$ 30.00	\$ 30.00
1 pc	Front o/s door checker	bent	\$ 121.00	\$ 121.00
2 pcs	Front o/s door hinge @\$94.00	bent	\$ 188.00	\$ 188.00
1 set	Front o/s door black sticker	necessary	\$ 60.00	\$ 60.00
1 pc	Rear o/s door	dented	\$ 1,260.10	\$ 1,260.10
1 pc	Rear o/s door outer protector	dented	\$ 299.10	\$ 299.10
1 pc	Rear o/s door inner lock	dented/ jammed	\$ 560.80	\$ 560.80
1 pc	Rear o/s door inner trim board	holder snapped	\$ 745.10	\$ 745.10
1 pc	Rear o/s door inner rubber	necessary	\$ 145.10	\$ 145.10
1 pc	Rear o/s door glass outer moulding	bent	\$ 132.50	\$ 132.50
1 pc	Rear o/s door glass regulator & motor	dented/ bent	\$ 388.00	\$ 388.00
1 pc	Rear o/s door outer handle	serviceable	\$ 245.10	\$ -
1 set	Rear o/s door black sticker	necessary	\$ 60.00	\$ 60.00
list parts c/f			\$ 10,491.50	\$ 9,790.60

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

Our Ref : PA/MI/21/1017/1

Veh. No. : SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

list parts b/f

\$ 10,491.50 \$ 9,790.60

1 pc	O/s centre pillar	dented	\$ 688.10	\$ 688.10
1 pc	Rear o/s fender	dented	\$ 1,160.10	\$ 1,160.10
1 pc	Rear o/s fender inner trim	serviceable	\$ 244.80	\$ -
1 pc	Rear bumper	deformed	\$ 561.50	\$ 561.50
1 pc	Rear bumper lower skirting	deformed	\$ 680.00	\$ 680.00
1 pc	O/s taillamp	cracked	\$ 380.10	\$ 380.10
1 pc	O/s rocker panel	dented	\$ 788.20	\$ 788.20
1 pc	O/s rocker panel outer skirting	cracked	\$ 650.50	\$ 650.50
1 pc	O/s rocker panel inner garnish	distorted	\$ 645.50	\$ 645.50
			<u>\$ 16,290.30</u>	<u>\$ 15,344.60</u>
Less 25%			<u>\$ 4,072.58</u>	<u>\$ 3,836.15</u>
			<u>\$ 12,217.73</u>	<u>\$ 11,508.45</u>

S/NETT PARTS

1 set	Front o/s fender inner shield clip	necessary	\$ 50.00	\$ 50.00
1 set	Front o/s door inner trim board clip	necessary	\$ 50.00	\$ 50.00
1 set	Rear o/s door inner trim board clip	necessary	\$ 50.00	\$ 50.00
1 pc	Rear windscreen glass sealant	necessary	\$ 50.00	\$ 50.00
1 pc	Rear windscreen inner seal	necessary	\$ 50.00	\$ 50.00
1 set	Rear bumper clip	necessary	\$ 50.00	\$ 50.00
1 pc	Front o/s sport rim	dented	\$ 800.00	\$ 500.00
1 pc	Rear o/s sport rim	dented	\$ 800.00	\$ 500.00
1 set	O/s door visor	necessary	\$ 100.00	\$ 100.00
			<u>\$ 2,000.00</u>	<u>\$ 1,400.00</u>

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

Our Ref : PA/MI/21/1017/I

Veh. No. : SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

To disconnect and check electrical wiring,
harness, wire sockets, etc.

To remove and reinstall damaged parts, test
and rectify for proper functioning.

\$ 50.00 \$ 30.00

To check and re-adjust computerised wheel
alignment.

\$ 150.00 \$ 100.00

To remove and replace front and rear o/s
sport rims and carry out wheel balancing.

\$ 80.00 \$ 50.00

To remove and replace front and rear o/s
door panels including transfer of fittings and
mechanism.

\$ 180.00 \$ 150.00

To remove and refix inner trims, garnishes,
linings and upholstery to facilitate repairs.

\$ 150.00 \$ 100.00

To remove and refix rear windscreen glass
to facilitate repairs and perform water test.

\$ 150.00 \$ 120.00

To mount vehicle onto chassis alignment
bench and to reset chassis alignment to
recommended specification.

\$ 380.00 \$ 380.00

To apply rustproofing, reseal tuff-coating
treatment to replaced/ repaired parts and
panels.

\$ 150.00 \$ 150.00

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Huat Automobile Air Con Service
Block 3007 #01-404
Ubi Road 1
Singapore 408701

Our Ref : PA/MI/21/1017/1

Veh. No. : SJK 6462 J

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

To remove and refix fuel tank to facilitate repairs.

\$ 100.00 \$ -

To remove and replace damaged parts as listed above including reinstatement of the necessary attachments and fittings to facilitate repairs. Jack up, straighten, panel beat and reshape the affected parts and components. To correct and realign the necessary parts.


\$ 1,800.00 \$ 1,600.00

To putty and spray painting on damaged portion including touch up paint on accident affected areas.

\$ 2,000.00 \$ 1,800.00

\$ 19,407.73 \$ 17,388.45

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum \$ 13,900.00** corresponding to supply of parts, labour and spray painting charges.



CHUAH POH SIONG GARY
CAE, MIMI, AMSOE,
AMIRTE, AMSAE-AUS, MSAAA

PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT
Automobile Appraisal Services



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021




Perfect Automobile Appraisal Services

PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021





Mobile Appraisal Services
Perfect Appraisal

PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021





PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021






PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021



PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: SJK 6462J

Re-inspection Photos

Date Of Accident: 18 August 2021



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	834G
Vehicle Details	
Vehicle No.:	SJK6462J
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	3ZZ4804582
Chassis No.:	MR053ZEE106121425
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	29 Oct 2008
First Registration Date:	29 Oct 2008
Transfer Count:	0
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Oct 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$30,284.00
COE Rebate Amount:	\$21,679.00
Total Rebate Amount:	\$21,679.00

The information contained herein is correct as at 20 Aug 2021

OK

Vehicle Details

Vehicle No.	Make / Model
SJK6462J	TOYOTA / COROLLA ALTIS 1.6 AUTO
Vehicle Type :	Vehicle Attachment 1 :
P10 - Passenger Motor Car	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MR053ZEE106121425
Propellant :	Engine No. :
Petrol	3ZZ4804582
Motor No. :	Engine Capacity :
-	1598 cc
Power Rating :	Maximum Power Output :
-	80.0 kW (107 bhp)
Maximum Laden Weight :	Unladen Weight :
1630 kg	1195 kg
Year Of Manufacture :	Original Registration Date :
2008	29 Oct 2008
Lifespan Expiry Date :	COE Category :
-	A - Car (1600cc & below)
PQP Paid :	COE Expiry Date :
\$30,284.00	28 Oct 2028
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
28 Oct 2021	-
Inspection Due Date :	Intended Transfer Date :
28 Oct 2021	31 Aug 2021
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-
CO Emission :	HC Emission :

NOx Emission :

PM Emission :

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (29 Oct 2021 to 28 Apr 2022)	\$408.00
Road Tax Renewal - 12 months (29 Oct 2021 to 28 Oct 2022)	\$888.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service [Enquire Road Tax Payable](#) to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

This vehicle has a road tax Over Payment of \$35.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Printed on 20 Aug 2021 09:31:45

Copyright © Land Transport Authority of Singapore 2021



Thank you

Khoo Ling Ling has successfully logged out.

Your last login date and time was 19 Aug 2021, 17:13:47.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	XE4566Y	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	19 Aug 2021 / 17:14:42

21.0627