

ASS. REC. BY:

Steve

CS3: / CRB 21910077 / EVF3

ASSIGNMENT

From:

PRS

Date:

Veh No:

FBK 1759G

Yr Reg:

6/4/05

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor /

Truck / Trailer or

OP / TP / WS / PR / RES / OD / RES / EVA / INV / MV

Make:

Yamaha FZS 100J

C.B. 599

To inspect Vehicle No:

Colour:

Red

A/C: Insured / Std / NI / N

at Workshop m/s

Sp. Reading

N/A

T/Radio: Insured / Std / NI / N

Insured:

Eng/No:

JYARN 14 1099 04080

Policy No.

C/No:

Gen. Cond: Good / Fair / Poor / Bupl

Claims No.

Steering: In order / Jammed / Locked / Burnt or

Sum Insured:

Excess:

Brakes: In order / Jammed / Locked / Burnt or

(Client's Record)

Mod: Nil / S/Rim / STD AIR / or

Make of Veh:

Tyre Size:

F:

R:

120/72R17

180/55ZR19

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Ret. or Market Value:

Front

R/Bal:

4

mm

Rear

R/Bal:

4

IDAC Accident Report

Consistent? : Yes or No

U/Bal:

mm

U/Bal:

SIA / PR Sent

Consistent? : Yes or No

D.O.A.

21/9/21

RWAVE

D.O.A.

28/9/21

Est. Repairs:

days

Res.: Yes or No

Sum Surc

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV- 4K

Time/Type, File Press 107

: Prel. Report

: Final Report

Time/Type, File Return 107

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S. + RS. \$

Photo

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Inve (\$

: Weekend (\$

Special Form:

WIP 2000 / 10.1.1