

ASS. REQ. BY:

Steve

CS3: / CRB 21910077 / EVF3

ASSIGNMENT

From:

PRS

Date:

Veh No:

FBK 17596

Yr Reg:

6/4/05

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor / 998

OP/TP/WS/TPRES/OD-RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

Make:

Yamaha FZS 100J

C.B.

599

at Workshop m/s

Colour:

Red

A/C: Insured / Std / NI / N

ul

Sp. Reading

N/A

T/Radio: Insured / Std / NI / N

Insured: SLT 641C

Eng/No:

C/No:

JYARN 14 1099 04080

Policy No. D21MFL0000447

Gen. Cond: Good / Fair / Poor / Bupl

Claims No. MFL2021D0004118

Steering: In order / Jammed / Locked / Burnt or

Sum Insured:

Excess:

Brakes: In order / Jammed / Locked / Burnt or

(Client's Record)

Mod: Nil / S/Rim / STD AIR / Rim or

Make of Veh:

Tyre Size:

F:

R:


120/72R17

180/55ZR19

(Policy Condition)

BS DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

Remarks: The veh had commenced its repair at the time of inspection.



Ret. or Market Value:

Front

Rear

IDAC Accident Report

Consistent? : Yes or No

R/Bal.

4

mm

R/Bal.

4

SIA / PR Sent

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

Est. Repair:

3

days

Res.: Yes or No

D.O.A.

21/9/21

RWAVE

D.O.A.

28/9/21

Sum Sure

29/9/21 steve

3 Val.: Yes or No

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roofing or

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date: Person Contacted:

Date / Time	Action / Instruction
	MV- 4K
29/9/21	Submit PRS

Time/Type, File Press 107

: Prel. Report

: Final Report

Time/Type, File Return 107

29/9/21-typist

Days Of Repair: 3

Resurvey No. of Trips:

Survey Fee:

Transportation

S. & RS. \$1

Photo

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Inve (\$

: Weekend (\$

Special Form:

WIP 2001/10/1/1