

ASS. REC. BY:

REF:

CTI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHR7591J

Yr Regn:

2019, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Tax) / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1798

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STDKRB3F4 80.3081455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Weste

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

12/9/21/21130

Survey held at

Trans Cab into

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Battery weak

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.H. ()

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7591J**AAD2109-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB7591J

JTDKB3FU803081455

TOYOTA

PRIUS

12/09/2021

CHINA

27/06/2019

PART**LIST**

1 COVER, REAR BUMPER	\$	de	442.60
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	bt	332.70
1 COVER, REAR BUMPER, LOWER	\$	de	15.40
1 GUARD, REAR BUMPER, CENTER	\$	de	576.30
1 RETAINER, REAR BUMPER SIDE, LH	\$	de	116.50
1 RETAINER, REAR BUMPER SIDE, RH	\$	de	117.70
1 FILLER, REAR BUMPER EXTENSION, RH	\$	Rx	123.70
1 FILLER, REAR BUMPER EXTENSION, LH	\$	de	123.70
1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	\$	as	54.40
1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$	as	54.40
1 MOULDING SUB-ASSY, ROOF TOP	\$	as	656.90
1 GLASS, BACK DOOR	\$	brw	1,656.70
1 PANEL SUB-ASSY, BACK DOOR	\$	bt	1,147.80
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	aq	925.60
1 COVER, REAR COMBINATION LAMP, RH	\$?	64.50
1 COVER, REAR COMBINATION LAMP, LH	\$?	64.50
1 BOARD ASSY, BACK DOOR TRIM	\$?	259.20
1 WEATHERSTRIP, BACK DOOR	\$	twi	372.30
1 BOARD, BACK DOOR TRIM	\$?	225.20
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$	ang	443.30
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$?	451.80
1 LENS AND BODY, REAR LAMP, LH upper	\$	ava	502.00
1 LENS AND BODY, REAR LAMP, RH upper	\$	ava	502.00
1 BOX, DECK FLOOR, RH	\$?	313.60
1 BOX, DECK FLOOR, LH	\$?	313.00
1 BOARD, REAR FLOOR, NO.1	\$?	519.00
1 BOX, DECK FLOOR, REAR	\$?	105.80
1 SEAL, REAR BUMPER SIDE, RH	\$?	88.50

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2109-**SHB7591J**

1 COVER, FLOOR UNDER, NO.1 (LH)	\$	de- 175.10
1 COVER, FLOOR UNDER, NO.2 (RH)	\$	amb- 241.90?
1 COVER, REAR FLOOR (CTR)	\$	amb- 229.90
1 COVER, DECK TRIM, REAR	\$? 126.70
1 PAN, REAR FLOOR	\$	Rx 583.40
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	bt- 651.00
1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$? 467.00
1 SWITCH ASSY, BACK DOOR OPENER	\$	x 179.10
1 COVER, BACK DOOR LOCK	\$? 30.20
1 SEAL, REAR BUMPER SIDE, LH	\$? 88.50
1 SPOILER, SUB ASSY, REAR	\$	amb- 1,575.40
1 LAMP SET, STOP CENTER	\$	amb- 192.30
1 STAY ASSY, BACK DOOR, LH	\$? 242.50
1 STAY ASSY, BACK DOOR, RH	\$? 242.50
1 HINGE ASSY, BACK DOOR, LH	\$	bt- 61.00
1 HINGE ASSY, BACK DOOR, RH	\$	bt- 61.00
1 HANDLE, DOOR PULL	\$	x 23.40
1 COVER, FRONT BUMPER	\$	de- 516.00
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	x 47.50
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	x 47.50
1 BRACKET, FRONT BUMPER SIDE, LH	\$? 59.30
1 BRACKET, FRONT BUMPER SIDE, RH	\$? 59.30
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$? 716.60
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	x 246.10
1 ABSORBER, FRONT BUMPER, LOWER	\$? 132.70
1 ABSORBER, FRONT BUMPER ENERGY	\$? 79.60
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	x 80.10
1 SUPPORT, FRONT BUMPER SIDE, LH	\$	x 82.30
1 COVER, ENGINE UNDER, NO.1	\$	x 472.40
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	x 241.90
1 EXTENSION, FRONT BUMPER, RH	\$	x 120.10
1 EXTENSION, FRONT BUMPER, LH	\$	x 120.10
1 COVER, FRONT BUMPER HOLE, LH	\$	x 29.30
1 COVER, FRONT BUMPER HOLE, RH	\$	de- 29.30
1 LAMP ASSY, FOG, LH	\$	x 951.40
1 LAMP ASSY, FOG, RH	\$	x 951.40
1 UNIT ASSY, HEADLAMP, LH	\$? 2,637.60

Trans-cab Auto Services Pte Ltd**AAD2109-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7591J

1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	X 960.50
1	UNIT ASSY, HEADLAMP, RH	\$	eng 2,637.60
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$? 960.50
1	GRILLE SUB-ASSY, RADIATOR	\$	346.00
1	GRILLE, RADIATOR, LOWER NO.1	\$	170.10
1	EMBLEM ASSY, RADIATOR GRILLE	\$	eng 90.80
1	FENDER SUB-ASSY, FRONT RH	\$	RY 977.80
1	LINER, FRONT FENDER, RH	\$	X 206.70
1	EMBLEM, SIDE PANEL	\$	eng 54.60
1	FENDER SUB-ASSY, FRONT LH	\$	RY 977.80
1	LINER, FRONT FENDER, LH	\$	X 202.50
1	EMBLEM, SIDE PANEL	\$	eng 54.60
1	HOOD SUB-ASSY	\$	bul 983.10
1	HINGE ASSY, HOOD, LH	\$	158.90
1	HINGE ASSY, HOOD, RH	\$? 58.90
1	BRACE, HOOD LOCK SUPPORT	\$? 78.30
1	INSULATOR, HOOD	\$	del 410.90
1	LOCK ASSY, HOOD	\$	gms 135.00
1	SEAL, HOOD TO FRONT END PANEL	\$	cut 51.60
1	HORN ASSY, HIGH PITCHED	\$? 134.80
1	HORN ASSY, LOW PITCHED	\$? 134.80
1	INLET, AIR CLEANER, NO.1	\$? 155.60
1	INLET, AIR CLEANER, NO.3	\$? 42.10
1	INLET, AIR CLEANER, NO.2	\$? 112.70
1	HOSE, AIR CLEANER, NO.1	\$? 74.00
1	JAR ASSY, WINDSHIELD WASHER	\$? 219.10
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$? 292.40
1	CONDENSER ASSY, COOLER	\$? 1,783.20
1	CLEANER ASSY, AIR	\$? 1,147.00

TOTAL \$ 36,872.40**25% \$ 9,218.10****\$ 27,654.30****Special Nett**

1SET PARKING AID	\$	200 mm 700.00
1SET REAR BUMPER CLIP	\$	30 95.00
2 WINDSCREEN SEALANT	\$	120 150.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2109-**SHB7591J**

1 WINDSCREEN MOULDING	\$	200.00	ref
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	ref
1 REAR TAILGATE TOYOTA LOGO	\$	47.90	ref
1 REAR TAILGATE WORDING 'PRIUS'	\$	54.60	ref
1 REAR TAILGATE WORDING 'HYBRID'	\$	54.60	ref
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	ref
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	ref
1 REAR BUMPER PROTECTOR	\$	180.00	60. ref
2 SEAM SEALANT	\$	250.00	X
1SET REAR FENDER LINER CLIP	\$	85.00	3one
1SET REAR BUMPER RETAINER CLIP	\$	85.00	3one
1 REAR NUMBER PLATE WITH HOLDER	\$	140.00	X
1SET TAILLAMP LOWER CLIP	\$	55.00	} 3one
1SET TAILLAMP UPPER CLIP	\$	55.00	
1 END PANEL TRIM CLIP	\$	65.00	2one
1 REAR SPOILER CLIP	\$	70.00	2one
1SET BUMPER CLIP FRT	\$	95.00	3one
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	X
1SET CLIP, FRONT FENDER LINER	\$	85.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
1 HOOD INSULATOR CLIP	\$	55.00	2one
1 Engine Under Cover Clip	\$	60.00	X
TOTAL	\$	3,157.10	
TOTAL PARTS	\$	30,811.40	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	18one
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	1400

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7591J**AAD2109-**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00 ³⁰
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00 ⁶⁰
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00 ³⁰
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00 ^X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00 ^{100? plus -}
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 ^{250? plus}
To check steering geometry and computer wheel alignment	\$	220.00 ^X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00 ⁶⁰
Towing Fees	\$ ^{towing receipt.}	150.00 ⁶⁰
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00 ¹⁶⁰⁰
To reinstall rear bumper parking sensor.	\$	170.00 ³⁰
To Check Electrical Lighting Concerned.	\$	170.00 ³⁰
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00 ⁶⁰
To transfer of tire, rim and on wheel balancing.	\$	220.00 ^X
To replace, refix and top up coolant for radiator	\$	170.00 ^{100?}

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7591J**AAD2109-**

To lift-up / out engine with gear box and refit.	\$	300 ? 440.00
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	photo X 380.00
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	Report 200 ? 380.00
TOTAL	\$	10,290.00
Over All Total	\$	41,101.40

(PART-BY-PART) Repair Days**25 DAYS**

Taufik 97495749

'WP' 17/9/21 @ 1130

* To check repair unit
* To provide taxi book value
10 days

taufik@lkkauto.com

* Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHB7591J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

15 Sep 2021

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS SDR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2C29191

Chassis No.:

JTDKB3FU803081455

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

27 Jun 2019

First Registration Date:

27 Jun 2019

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

26 Jun 2027

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

26 Jun 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$23,872.00

COE Rebate Amount:

\$17,249.00

Total Rebate Amount:

\$27,934.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Sep 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/09/2021 22:17 (SGT)
Date of Accident	12/09/2021 11:53 (SGT)
Exact Location of Accident	Near PIE, Singapore
Additional Location Information	Kallang Paya Lebar expressway
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7591J
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666
VEHICLE PARTICULARS	
Manufacturer	Toyota
Model	PRIUS 5 DR HATCHBACK (AUTO)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767
INSURANCE COMPANY	
Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	-
DRIVER	
Name of Driver	Kek Koon Sye
NRIC No	SXXXX501Z

Date Of Birth	19/05/1963
Occupation	Outdoor
Date Of Driving Pass	11/05/1996
Driving experience	25 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98938275
Alt. Phone Number	-
Email Address	kekkoonsye@gmail.com
Address	348 Kang Ching
Address complement	#05-155
Postcode	610348
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	P1
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong West Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002689999
Alt. Police Station Phone No	(Fax) +65-62672438
Police Station Address	700 Corporation Road Singapore 649818
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer as police reports T/20210913/2052)

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	SD WITH TP
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2492E
-----------------------------	---------



SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER**
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

ACCIDENT DIAGRAM Ver. 30042021

KPE SIMS

Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SINGAPORE POLICE FORCE

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649618
Tel No: 1800-2689999

1 of 3
Report No: 9/20210913/2963

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/09/2021 14:37 Vide Report No: Station Diary No: 117

Informant's Particulars

Name of Informant: KEK KOON SYE Address: APT BLK 348 KANG CHING ROAD #05-155 SINGAPORE 610348 Mobile: 98938275

ID Type / ID No: Contact No: Home/Office: Email: Institution / School Name: Date of Expiry: Driving Licence Information: Class 2B 2A 3

Nationality: SINGAPORE CITIZEN Sex: Male Age: 58 Date of Birth: 19/05/1963 Race: Chinese Occupation: Taxi driver

General Information of the Accident

Type of Accident: Injury Conveyed By Ambulance: Drink Drive No: Date/Time of Accident: 12/09/2021 11:50 Type of Location: X-Junction

Location: KALLANG PAYA LEBAR EXPRESSWAY

Weather: Clear Road Surface: Dry Road Speed Limit: Traffic Volume: Heavy Anyone conveyed by ambulance: Yes

Traffic Flow: One Way Traffic Control: Not Controlled

Type of Collision: Between Moving Vehicles - Head To Rear

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBC6187R	Lorry	TOYOTA	DYNA 150 5MT	Silver	Slightly Damaged	3
SHB7591J	Car	TOYOTA	PRIUS 5DR HATCHBACK (AUTO)	Red	Seriously Damaged	1
YN2492E	Lorry	MITSUBISHI	FE83BE6SR DEA	White	Slightly Damaged	7



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C.
700 Corporation Road SINGAPORE 649818
Tel No. 1800-2689999



T2002100913/2052

2 of 3

Report No. 1-20210913-2052





CONTINUATION OF REPORT

Brief Details.

On 12/09/2021 at about 1153hrs, I was driving my taxi, SHB7591J along Kallang Payar Lebar Expressway (KPE) heading towards Sims Way. I observed the vehicles were slowing down to merge into Sims Way and I also slowed down. Suddenly, I felt an impact from the rear (YN2492E) and the momentum brought my taxi forward which collided into the lorry (GBC6187R) in front of me. I exited my vehicle and took down the vehicle numbers and the two lorry drivers drove off without giving me their particulars and contact info. I have a female passenger in my taxi and we both felt pain on our body due to the collision. I feel pain on my spinal area and shoulders. I have a working in car camera recording the accident.

LTA Officer (road marshal) and ambulance was at scene. I was conveyed to Tan Tock Seng Hospital and was admitted on 12/09/2021 and discharged on 13/09/2021. I received 7 days medical certificate from 12/09/2021 to 18/09/2021. I would like to state that I am unsure of my female passenger particulars. I am unable to trace her Grab Booking ID and that she was also conveyed to hospital by ambulance at scene. The two lorries had several passengers in their vehicles.

My taxi was badly damaged and had to be towed by TP.

 SINGAPORE POLICE FORCE Police Station Of Origin: Jurong West N.P.C. 700 Corporation Road SINGAPORE 649816 Tel No: 1800-2689999		 Report No: 1-21210913-0102 3 of 3
CONTINUATION OF REPORT		
Sketch Plan Informant is not able to provide sketch plan		
IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.		
Signature of Officer Recording The Report J / Sgt 3 SITI KHAIRUNNISA BINTE RAMANAH	Signature Of Informant 	
Signature Of Interpreter Not applicable	Date/Time 13/09/2021 14:37	
Officer In Charge Of Case TP / GIT / Sgt 3 MUHAMMAD FARHAN BIN SAIRI Contact No: 65476224	Classification Of Case:	
Authentication Stamp  Signature: _____ Singapore Police Force		
		SN 126