

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21010033/Bgs3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	20/12/2021	
	ATTN:YVONNE			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 962Z	Veh. Inspected		EW 63M	
	Policy No.	P2419140	Coverage (\$)		0.00	
	Claim No.	S1M03I8Z	Excess (\$)		0.00	
	Assign From		Assign Date		27/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VELLFIRE	c.c		2493	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	AGH300204871	Colour		BLACK	
	Odometer	40262 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	255/35 R20	FALKEN		6 mm	
	L/H Front Tyre	255/35 R20	FALKEN		6 mm	
	R/H Rear Tyre	255/35 R20	FALKEN		6 mm	
	L/H Rear Tyre	255/35 R20	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/09/2021	Inspection Dat	е	28/09/2021	
	Survey held at	TEAM AUTOPRO PTE LTD				
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	