



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21010043/Aqf3s2	Date: 25/05/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJN 8152A	Veh. Inspected	SLU 9466C	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011834/EE	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	28/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI TUCSON	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHJ3812VJU628029	Colour	BLUE	
Odometer	31998 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	KUMHO	6 mm	
L/H Front Tyre	225/60 R17	KUMHO	6 mm	
R/H Rear Tyre	225/60 R17	KUMHO	6 mm	
L/H Rear Tyre	225/60 R17	KUMHO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/09/2021	Inspection Date	28/09/2021	
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	