

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Steve (LKK)
29/9/21, 10.00am

Mr L NL
3 days
P/P
My Bel my

Quotation

Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Company
KWH
MARKETING PTE LTD
9 THIRD LOK YANG ROAD
SINGAPORE 628004

Document no.
Document date 27-09-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021036656/ 1
Job order date 27-09-2021
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMM3994P	3G24JZC0	27-06-2019	WVWZZZ3CZKE080931	Passat Comfortline 1.8 TSI 132kW DSG	35,727

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
3G0853687 2ZZ	Inscription Bright Chrome NAME PLATE - PASSAT		pcs.	75.93	#1	75.93	81.25
3G5807417 GRU	Cover Primed	1	pcs.	1,720.21	#1	1,720.21	1,840.62
3G0807521B GRU	Spoiler Primed	1	pcs.	295.43	#1	295.43	316.11
3G0807305T	Bumper REINFORCEMENT	1	pcs.	661.70	#1	661.70	708.02
N 90346302	Pop-Rivet	10	pcs.	1.23	#1	12.30	13.16
3G5807863	Attachment Strip BUMPER CTR BRACKET	1	pcs.	63.45	#1	63.45	67.89
3G5807483A	Guide LHS BUMPER BRACKET (UPPER)	1	pcs.	23.81	#1	23.81	25.48
3G5807484A	Guide RHS BUMPER BRACKET (UPPER)	1	pcs.	23.81	#1	23.81	25.48
3G5807375	Guide Piece LHS BUMPER BRACKET (SIDE)	1	pcs.	40.70	#1	40.70	43.55
3G5807376	Guide Piece RHS BUMPER BRACKET (SIDE)	1	pcs.	40.70	#1	40.70	43.55
3G0998491	1 Set Sensor Brackets	1	pcs.	45.72	#1	45.72	48.92
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.16	#1	81.16	86.84
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.18	#1	65.18	69.74
3G0853835 2ZZ	Decorative Moulding Brigh BUMPER CTR LOWER MLDG CHROM		pcs.	225.19	#1	225.19	240.95
3G0853841 2ZZ	Decorative Moulding Brigh LHS BUMPER LOWER MLDG CHROM		pcs.	172.87	#1	172.87	184.97
3G0945105A	Reflector LHS REFLECTOR OUTER	1	pcs.	69.48	#1	69.48	74.34
3G0945103A	Reflector LHS REFLECTOR INNER	1	pcs.	69.48	#1	69.48	74.34
	LABOUR	3	pcs.	840.00	#1 840	2,520.00	2,696.40
	SPRAY PAINT	4	pcs.	800.00	#1 800	3,200.00	3,424.00
	SOMPO VS INDIA						
	3RD PARTY VEHICLE SML5521M						
	D.O.A: 18-09-2021						
	SURVEY BY:						

Quotation valid till 04-10-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	9,407.12	7%	711.70	10,167.12	10,878.82
Total	760.00	9,407.12		711.70	10,167.12	10,878.82

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Company
KWH
MARKETING PTE LTD
9 THIRD LOK YANG ROAD
SINGAPORE 628004

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

27-09-2021
5211000972
198703792K
30001
2021036656/ 1
27-09-2021
YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMM3994P	3G24JZC0	27-06-2019	WWWZZZ3CZKE080931	Passat Comfortline 1.8 I TSI 132kW DSG	35,727

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
----------	--------	----------	-------	-----	------------------------	------------------------

Customer



-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: