



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLX6129E MAZDA 3 SEDAN 1.5 AT LED EU6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Center grille top panel <i>de</i>		330.00	
1	Center grille top inner panel garnish <i>?</i>		96.00	
1	Center grille assy <i>cm</i>		589.00	
1	Center grille logo badge base <i>cm</i>		22.00	
1	Center grille logo badge <i>cm</i>		62.00	
2	Center grille lower side outer chrome LH/RH @2*\$192 <i>?</i>		384.00	
2	Center grille lower side outer chrome base LH/RH @2*\$21 <i>?</i>		42.00	
2	Center grille inner side top bracket LH/RH @2*\$28 <i>?</i>		56.00	
1	Front bumper <i>de</i>		867.00	
2	Front bumper side bracket LH/RH @2*\$20 <i>?</i>		40.00	
1	Car plate base garnish <i>cm</i>		75.00	
1	Front bumper lower grille side cover rh <i>mis</i>		37.00	
1	Front reinforcement <i>?</i>		503.00	
1	Boot lid <i>X</i>		1006.00	
1	Boot lid lock <i>X</i>		161.00	
1	Boot lid emblem "Mazda 3" <i>X</i>		57.00	
1	Boot lid emblem "skyactiv" <i>X</i>		67.00	
1	Boot lid logo badge <i>X</i>		79.00	
1	Rear bumper <i>de</i>		997.00	
2	Rear bumper side retainer LH/RH @2*\$38 <i>X</i>		76.00	
1	Rear bumper towing cover rh <i>mis</i>		18.00	
1	Rear reinforcement <i>?</i>		565.00	
1	End panel <i>X</i>		531.00	
1	End panel top garnish <i>X</i>		90.00	
1	Rear reverse sensor LH/RH @2*\$204 <i>?</i>		408.00	<i>200?</i>
Part Items Total:			7158.00	
			-20% -1431.60	
			5726.40	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>mi</i>		35.00	<i>30</i>
1	Center grille clips <i>mi</i>		35.00	<i>30</i>
1	Front bumper riveting <i>mi</i>		50.00	<i>30</i>
1	Front bumper clips <i>mi</i>		35.00	<i>30</i>
1	End Panel sealant <i>X</i>		60.00	<i>X</i>
1	Coolant <i>X</i>		60.00	<i>X</i>
1	Front Car plate number <i>cm</i>		35.00	
SN Items Total:			310.00	
Total Parts			6036.40	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLX6129E MAZDA 3 SEDAN 1.5 AT LED EU6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	500
3	To perform anti-rust treatment on affected areas	60.00 X	
4	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	60
5	To remove and replace rear reverse sensor	60.00 /	
6	To remove and refit rear seat compartment fitting, trimmings, garnish and etc	100.00 X	
Labour Total :		2510.00	
TOTAL (PARTS & LABOUR):		8546.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame

Hy 90010068

5 days

L/S

28/09/21 @1520

Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/09/2021 15:30 (SGT)
Date of Accident	25/09/2021 13:29 (SGT)
Exact Location of Accident	Near 1 Bukit Batok Street 22, Singapore 659592
Additional Location Information	BT BATOK EAST AVE 6 TOWARDS BT BATOK AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX6129E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEE SHI HUI
NRIC No	SXXXX753H
Email Address	LSH1992WCG@GMAIL.COM
Mobile Phone No	(Phone) +65-90491538
Alternative Phone No	+65-90491538

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	FWD Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	PNPV2020-00004081-01
Cover Note Number	-

DRIVER

Name of Driver	CHUA MING XUAN
NRIC No	SXXXX147D

Date Of Birth 05/06/1992
 Occupation Indoor
 Date Of Driving Pass 26/03/2012
 Driving experience 9 YEARS AND 6 MONTHS
 Gender Male
 Mobile Number (Phone) +65-96226988
 Alt. Phone Number -
 Email Address CMX1992@GMAIL.COM
 Address BLK 453A BUKIT BATOK WEST AVENUE 6
 Address complement #11-755
 Postcode 651453
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Spouse
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 4
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC7125Y
 Vehicle Manufacturer Nissan
 Vehicle Model Nv350
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver GOVINDARAJ BAGAVATHIRAJ
 Contact Number (Phone) +65-90696374
 Address -
 Address complement -

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
	4

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
Vehicle Manufacturer	SMQ5448R
Vehicle Model	BMW
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	KISHEN S/O NIBALAGI
Address	(Phone) +65-96150495
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SG7003J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	JEBOT BIN MOHAMED
Contact Number	(Phone) +65-92333941
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A - SLX 6129E
B - PC 7125Y
C - SMQ 5448R
D - SG 7003J


Describe Circumstances of the Accident

Refer to video attached.
 Rear of Front Video.

Declaration

We declare the foregoing particulars are true in every respect.

 Policyholder's Signature / Date &
 Time


 Driver's Signature (If driver is not the policyholder) / Date
 & Time

 Witnessed by Reporting Centre
 Personnel



Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

753H

Vehicle Details

Vehicle No.:

SLX6129E

Vehicle to be Exported:

No

Intended Deregistration Date:

30 Sep 2021

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA3 SEDAN 1.5 AT LED EU6

Primary Colour:

Grey

Manufacturing Year:

2017

Engine No.:

P520492148

Chassis No.:

JM6BN22A8J0200617

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$18,017.00

Original Registration Date:

02 Apr 2018

First Registration Date:

02 Apr 2018

Transfer Count:

1

Actual ARF Paid:

\$18,017.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

01 Apr 2028

PARF Rebate Amount:

\$13,512.00

Intended COE Rebate Details

COE Expiry Date:

01 Apr 2028

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$38,000.00

COE Rebate Amount:

\$24,710.00

Total Rebate Amount:

\$38,222.00

The information contained herein is correct as at 25 Sep 2021

OK

Mazda 3 1.5A Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price **\$62,800**

Depreciation ?

\$8,660 /yr

[View models with similar depre](#)

Reg Date

19-Feb-2018

(6yrs 4mths 20days COE left)

Mileage

41,000 km (11.4k /yr)

Manufactured ?

2017

Road Tax ?

\$682 /yr

Transmission

Auto

Dereg Value ?

\$38,621 as of today (change)

OMV ?

\$14,934

COE ?

\$42,900

ARF ?

\$14,934

Engine Cap

1,496 cc

Power

88.0 kW (118 bhp)

Curb Weight ?

1,310 kg

No. of Owners ?

2