

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Tans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 7956R Yr Regn: 08, 19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pro c.c. 1798Colour M. P. White / R. A/C: Insured / Std / NI / NASp. Reading 193604 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTPKB 3F4 303 08-3033Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sailun

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 24/9/21 D.O.I. 27/9/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fr body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Grot BZ

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

\$ - RS. \$ _____

☐ : Interview (\$ _____)

Fuel: _____

☐ : Tech Invs (\$ _____)

Others: _____

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____