

|          |      |             |
|----------|------|-------------|
| 1 of 2 ? | 100% | Find   Next |
|----------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                        |                                                                                          |                 |                          |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-----------------|--------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                               |                                                                                          |                 |                          |  |
| INDIA INTERNATIONAL INSURANCE PL                                                                                                       |                                                                                          |                 | Ref: CS/III21010082/Atf3 |  |
| 64 CECIL STREET                                                                                                                        |                                                                                          |                 | Date: 29/09/2021         |  |
| #05-02 IOB BUILDING SINGAPORE 049711                                                                                                   |                                                                                          |                 | Code: III2               |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                          |                 |                          |  |
| Insured Veh.                                                                                                                           | SMN 763D                                                                                 | Veh. Inspected  | SJR 9933K                |  |
| Policy No.                                                                                                                             |                                                                                          | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                              |                                                                                          | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                            | BHUVANESWARI                                                                             | Assign Date     | 29/09/2021               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                          |                 |                          |  |
| Make & Model                                                                                                                           |                                                                                          | c.c             | 0                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                   | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                            |                                                                                          | Colour          |                          |  |
| Odometer                                                                                                                               | -                                                                                        | Steering        |                          |  |
| Brakes                                                                                                                                 |                                                                                          | Modification    |                          |  |
| General                                                                                                                                |                                                                                          |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                          |                 |                          |  |
|                                                                                                                                        | Size                                                                                     | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                         |                                                                                          |                 | mm                       |  |
| L/H Front Tyre                                                                                                                         |                                                                                          |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                          |                                                                                          |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                          |                                                                                          |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                          |                 |                          |  |
|                                                                                                                                        |                                                                                          |                 |                          |  |
| <b>5. General Information</b>                                                                                                          |                                                                                          |                 |                          |  |
| Accident Date                                                                                                                          | 25/09/2021                                                                               | Inspection Date | 29/09/2021               |  |
| Survey held at                                                                                                                         | AUTOMOBILE HUB ENTERPRISE<br>1 KAKI BUKIT AVENUE 6<br>#02-11 AUTOBAY<br>SINGAPORE 417883 |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                          |                 |                          |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                          |                 |                          |  |