

(08/11/13) Wef
ASS. REC. BY: *Rasm*

REF:

CS3/A1621010091/Rivf3

2446

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

4P5179E

at Workshop m/s

NKEE NKEE MOTOR

of

22 Pandan Loop

Insured:

AKH

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

51K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Repair limit - 28K

Veh No:

4P5179E

Yr Regn:

2016 / DGL

Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. DUBISHI CANTER FEB 21 C.C. 2998

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

103431

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEB 21 GA20168

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/85R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

24/09/21

D.O.I.

29/09/21

Survey held at

Pandan Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) : S + RS, SI

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/09/2021 16:24 (SGT)
Date of Accident	24/09/2021 22:50 (SGT)
Exact Location of Accident	New Bridge Rd, Singapore
Additional Location Information	New Bridge Road after Merchant Road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP5179E

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Edmund Vehicle Rental Pte Ltd
Company Reg No	201625244G
Email Address	edmundevr@gmail.com
Mobile Phone No	(Phone) +65-92222561
Alternative Phone No	(Home) +65-92222561

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Fuso
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2998

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5112254195-02-000180
Cover Note Number	-

DRIVER

Name of Driver	Muhammad Firdaus Bin Jamil
NRIC No	S8618377C

Date Of Birth	13/06/1986
Occupation	Outdoor
Date Of Driving Pass	06/06/2011
Driving experience	10 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92222561
Alt. Phone Number	-
Email Address	edmundevr@gmail.com
Address	279 Balestier Road Balestier Point #02-27
Address complement	-
Postcode	329727
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Yishun North Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008529999
Alt. Police Station Phone No	(Fax) +65-68522299
Police Station Address	31 Yishun Central Singapore 768827
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached police report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMN5525S
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Muhamad Dam Bin
(Phone) +65-96836442

-
-
-
-
-
-
-

Describe Circumstances of the Accident

AS SEE POLICE REPORT AND PLUMMER INFO FOOTAGE

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Central
Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

UN 55253





**SINGAPORE
POLICE FORCE**



L/20210925/2014

1 of 2

POLICE REPORT (NP299)

Report No. L/20210925/2014

Police Station Of Origin
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Date/Time Report Made 25/09/2021 08:36	Video Report No.	Station Diary No. 25
Name Of Informant MUHAMMAD FIRDAUS BIN JAMIL	Address APT BLK 325 YISHUN CENTRAL #03-347 SINGAPORE 760325	
ID Type / ID No. NRIC NO / S8618377C	Contact No. Home/Office Mobile 92222561	
Nationality SINGAPORE CITIZEN	Email Address	
Occupation DRIVER	Sex Male	Age 35
Institution/School Name	Date of Birth 13/06/1986	Race Javanese
Date/Time Of Incident 24/09/2021 22:50	Location Of Incident NEW BRIDGE ROAD SINGAPORE	
Brief details.		

- 1) I am working as a Driver for Wilson Parking Pte Ltd and drove a vehicle with the registration number (YP5179E) that was belongs to Rental Company.
- 2) On 24 September 2021 at about 2250hrs, I was driving along New Bridge Road on the center lane after Merchant Road and I was stationary at the traffic junction due to the traffic light.
- 3) However, there was a vehicle with the registration number (SMN5525S) came from the back and

Signature Of Officer Recording The Report:
L / Sgt 1 GAN WEI LEONG,
ALASTAIR

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
25/09/2021 08:36

Officer In-Charge Of Case:
L / Sembawang N.P.C /
Insp CHOO ZHENG JIE, MARCUS
Contact No.: 646660000

Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



L/20210925/2014

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20210925/2014

knocked onto the back of my vehicle.

4) I checked with the driver immediately and exchanged contact details and will proceed for our insurance claims as there were no injured party / no foreign vehicle involved and no government property damaged.

5) I am lodging this report for Rental Company record purposes.

6) I wish to state that there was a dent on the back of my vehicle due the collision.

Details of the Driver (SMN5225S)

Name: Muhamed Dani Bin Rodman

NRIC: Last Three Digit - 030G

Contact Number: 9683 6442.

Signature Of Officer Recording The Report:
L / Sgt 1 GAN WEI LEONG,
ALASTAIR

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
L / Sembawang N.P.C /
Insp CHOO ZHENG JIE, MARCUS
Contact No.: 646660000

Authentication Stamp

Signature Of Informant:

Date/Time:
25/09/2021 08:36

Classification Of Case:

Condition (CON)
 (01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

VAN / LORRY (Rear)

4P 5179E

ACTION (AC)
 (1) Replace (✓) (2) Repair (✓) (3) Check (?)
 (4) Not Consistent (NC)

Aug 2005

Rear Portion

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar	bf	/	
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	bf	/	
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	bro	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	bf	/	
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	scr	R	
2054	993700	Rear Rubber Stopper RH	scr	/	
2055	993701	Rear Rubber Stopper Bracket	bf	/	
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge	scr	/	1
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock RH	bf	/	
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel	bf	R	
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		Rear wooden pillar (side)	scr	R	
		Rear wooden pillar (rear)	cm	/	
		Hook	bf	/	2

5 days

No of Items:

Assessor:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	244G
Vehicle No.:	YP5179E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B96743
Chassis No.:	FEB21EA20168
Maximum Power Output:	-
Open Market Value:	\$29,849.00
Original Registration Date:	29 Dec 2016
First Registration Date:	29 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$1,493.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	28 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,774.00
COE Rebate Amount:	\$22,421.00
Total Rebate Amount:	\$22,421.00

The information contained herein is correct as at 30 Sep 2021

OK

Mitsubishi Fuso Canter FEB21

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$49,800	Lifespan ?	10-Oct-2036
Depreciation ?	\$9,900 /yr View models with similar depre	Reg Date	11-Oct-2016 (5yrs 10days COE left)
Mileage	N.A.	Manufactured ?	2016
Road Tax ?	N.A.	Transmission	Auto
Dereg Value ?	\$17,064 as of today (change)	Fuel Type	Diesel
COE ?	\$33,923	OMV ?	\$34,954
Engine Cap	2,998 cc	ARF ?	\$1,748
Curb Weight ?	2,480 kg	No. of Owners ?	1
Type of Vehicle	Truck		

Features

View specs of the Mitsubishi Fuso Canter Diesel (2015)