

ASS. REG. BY:

Steve

CC3/AIG 71010093/GA3

ASSIGNMENT

From:

Date:

Estimated Cost:

OR / TP / WS / TP RES / OD-REG / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

SIA / PR Sent:

Consistent? Yes or No

Est. Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

GA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMD 7212 J

Yr Regn:

31/8/18

Type (M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover)

Truck / Trailer or

Make:

Skoda Kodiak

CB 1395

Colour:

Grey

A/O: Insured / Std / NI / N

Sp. Reading

38149

TIRadio: Insured / Std / NI / N

Eng/No:

CRNo:

THARK CTN: S/T 809.7195

Gen. Condi: Good / Fair / Poor / Bupst

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F1

235/55R18

R1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

24/9/21

D.O.A.

4/9/21

Survey held at

Skoda Centre

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof/ceiling or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - UOK

Date/Time, File, Pass to?

Procl. Report

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Transportation

Add Fee:

Site Insp (\$

Interview (\$

Tech. Insp (\$

Workshop (\$

\$ + RS, SI

Printed

Checked

Final

TOTAL

Approved/Issued:

Date/Time/Signature

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
E Reg. No.: 199101494Z
G: T No.: M200985052



Steve (LKK)
4/10/21, 10.00am
ML RL
5 days
PIP
as per L sy

Quotation
Non binding - Preview

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
JOANNE LISA
PROBERT
530 EAST COAST ROAD
#05-04 OCEAN PARK
Singapore 458970

Page 1/2
Document no.
Document date 29-09-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021036468/ 1
Job order date 24-09-2021
Service Advisor SHU SHI TANG

License plate SMD7212J	Model code NS73LC	First registration 31-08-2018	VIN TMBKC7NS7J8097395	Model KODIAQ AMB TS110/1.4A6F	Mileage 37,757
---------------------------	----------------------	----------------------------------	--------------------------	----------------------------------	-------------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
565827023D	Rear Lid	1	pcs.	3,903.90	#1	3,903.90	4,177.17
D 169300M2	1k Window Adhesive	2	pcs.	51.16	#1	102.32	109.48
D 00940104	All Purpose Cleaner	1	pcs.	97.37	#1	97.37	104.19
D 00920002	Primer	1	pcs.	28.44	#1	28.44	30.43
D 181802M1	Activator For Precoated W	1	pcs.	26.15	#1	26.15	27.98
D 00950025	Applicator	1	pcs.	10.44	#1	10.44	11.17
WHT007341	Riveted Cap Nut	2	pcs.	2.50	#1	5.00	5.35
4M0827506D	Hood Latch	1	pcs.	249.05	#1	249.05	266.48
5JJ945097	BOOT LID LOCK High-Mount	1	pcs.	181.71	#1	181.71	194.43
565853621A FOD	3RD BRAKELIGHT Skoda Embl	1	pcs.	65.07	#1	65.07	69.62
5JA853687 2ZZ	Inscriptio NAME PLATE - SKODA	1	pcs.	73.51	#1	73.51	78.66
565853687A 2ZZ	Lettering NAME PLATE - KODIAQ	1	pcs.	99.42	#1	99.42	106.38
565807421	Cover For REAR BUMPER (UPPER)	1	pcs.	1,776.63	#1	1,776.63	1,900.99
565807521 9B9	Cover For REAR BUMPER (LOWER BLACK)	1	pcs.	520.87	#1	520.87	557.33
565919493A 9B9	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
565919494A 9B9	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
565919491C	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
565919491B	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
565919492B	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
565919492C	Sensor Bracket	1	pcs.	13.22	#1	13.22	14.15
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.18	#1	65.18	69.74
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.16	#1	81.16	86.84
565807423	Bump Strip	1	pcs.	228.23	#1	228.23	244.21
WHT000813	Double Collared Stud	2	pcs.	8.85	#1	17.70	18.94
565807251B	Foam Reinf	1	pcs.	132.06	#1	132.06	141.30
565807863	Retaining	1	pcs.	78.84	#1	78.84	84.36
565807393B	BUMPER CTR BRACKET Guide Piec	1	pcs.	46.98	#1	46.98	50.27
565807394B	LHR BUMPER BRACKET (UPPER) Guide Piec	1	pcs.	46.98	#1	46.98	50.27
565807393	RHR BUMPER BRACKET (UPPER) Guide Piec	1	pcs.	46.98	#1	46.98	50.27
565807394	LHR BUMPER BRACKET (SIDE) Guide Piec	1	pcs.	46.98	#1	46.98	50.27
	RHR BUMPER BRACKET (SIDE) LABOUR	5	pcs.	840.00	#1	4,200.00	4,494.00

1680

Centre Singapore
 Kee Rd
 159104
 Reg. No.: 199101494Z
 No.: M200985052



Quotation
 Non binding - Preview

Page 2/2

Company
 AIG ASIA PACIFIC INSURANCE P/L
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120

Customer Details:
 Ms.
 JOANNE LISA
 PROBERT
 530 EAST COAST ROAD
 #05-04 OCEAN PARK
 Singapore 458970

Document no.
 Document date 29-09-2021
 Customer no. 5211043795
 Customer GST-ID 201009404M
 Dealer 30001
 Job order number 2021036468/ 1
 Job order date 24-09-2021
 Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMD7212J	NS73LC	31-08-2018	TMBKC7NS7J8097395	KODIAQ AMB TS110/1.4A6F	37,757

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	SPRAY PAINT	47	pcs.	800.00	#1 1600	3,200.00	3,424.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	0.5	pcs.	840.00	#1 420	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	AIG DIRECT SETTLEMENT DOA: 24/09/2021 TP VEH: GBD8411A SURVEY BY:						

Quotation valid till 01-10-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	17,320.29	7%	1,265.62	18,080.29	19,345.91
Total	760.00	17,320.29		1,265.62	18,080.29	19,345.91

Customer

Service Advisor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval by Volkswagen, Skoda and www.skoda.com.sg (for additional services, products and promotions).

Acknowledged by Repairer

Signature:

Date:

All invoices are denominated in SGD, unless otherwise stated.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/09/2021 11:38 (SGT)
Date of Accident	24/09/2021 10:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BENCOOLEN ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD7212J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	JOANNE LISA PROBERT
NRIC No	SXXXX543H
Email Address	probertjo@yahoo.com
Mobile Phone No	(Phone) +65-92727790
Alternative Phone No	+65-92727790

VEHICLE PARTICULARS

Manufacturer	Skoda
Model	Kodiaq
Variant	KODIAQ AMB TS110/1.4A6F
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	P2186215
Cover Note Number	-

DRIVER

Name of Driver	JOANNE LISA PROBERT
NRIC No	SXXXX543H

Driving Pass
 Experience
 Number
 Phone Number
 Mail Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

04/09/1974
 Indoor
 11/10/2018
 2 YEARS AND 11 MONTHS
 Female
 (Phone) +65-92727790
 +65-92727790
 probertjo@yahoo.com
 530 EAST COAST ROAD
 #05-04
 458970
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD8411A
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver ONG HAN HSIANG
 NRIC No SXXXX149J
 Contact Number (Phone) +65-81130684
 Address -

Element
Company Name
Damage
of property damaged in accident
of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Jonnie P... [Signature]


[Signature] 26/4/2021

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 24TH SEPTEMBER AT APPROXIMATELY 10.50am
I WAS TRAVELLING ON BENCOOLEN ROAD.
AT THE JUNCTION WITH MIDDLE ROAD I WAS IN THE
CENTRE LANE OF FIVE LANES.
THE LIGHTS TURNED GREEN BUT A CAR PULLED
INTO THE JUNCTION FROM MIDDLE ROAD ON THE
RIGHT.
THE CAR IN FRONT OF MINE BRAKED SHARPLY.
I APPLIED MY BRAKES TO STOP AND A TOYOTA
VAN RAN INTO THE REAR OF MY CAR.

Declaration

We declare the foregoing particulars are true in every respect.

Jonnie Hibberd

24/9/2024