

ASS. REC. BY:

REF:

AIG/210101021kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB524914

Regn: 05, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Fiat Fiorino

c.c.

1248

Colour:

Silver

AC:

Insured / Std / NI / NA

Sp. Reading

126369

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZFA2250000 0059447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Falken

Continental 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/9/21

D.O.I.

30/9/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBB5249H
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000
 ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2190921/YISHUN
 Date: 29 Sep 2021
 Policy No: Z/21/VC00/110925
 Veh Reg No: GBB5249H
 Make/Model: FIAT FIORINO 1.3MJTD (225.2L20)
 Chassis No: ZFA22500000059447
 Engine No: 199A20003053439
 Reg. Date: 27/05/2009

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 28/09/2021
 TP Veh Reg No: GBL1338H

Not Mechanical

1/1 Rng & Presum After Rainy Today

Estimate Repair Cost to Vehicle No :GBB5249H

Description	U/Price	Quantity	List Price	Amount
			\$S	\$S
List Price				
1 REAR BUMPER	750.00	1 PC	R ₁ 750.00	✓
2 REAR BUMPER REINFORCEMENT	480.00	1 PC	480.00	✓
3 LH TAILGATE	1,680.00	1 PC	R ₁ 1,680.00	✓
4 TAILGATE EMBLEM (FIORINO)	60.00	1 PC	R ₁ 60.00	✓
5 TAILGATE OUTER HANDLE	90.00	1 PC	R ₁ 90.00	✓
6 TAILGATE INNER LOCK	340.00	1 PC	T ₁ 340.00	✓
7 TAILGATE INNER BOARD	185.00	1 PC	D ₁ 185.00	✓
8 TAILGATE GLASS LH	470.00	1 PC	470.00	✓
9 TAILGATE GLASS INNER LOCK LH	380.00	1 PC	T ₁ 380.00	✓
10 TAILGATE GLASS INNER BOARD LH	190.00	1 PC	R ₁ 190.00	✓
11 TAILGATE INNER RUBBER LH	190.00	1 PC	190.00	✓
12 REAR WIPER ARM	125.00	1 PC	R ₁ 125.00	✓
13 REAR WIPER ARM CAP	25.00	1 PC	R ₁ 25.00	✓
14 TAILLAMP LH	385.00	1 PC	385.00	✓
15 RH TAILGATE	1,750.00	1 PC	R ₁ 1,750.00	✓
16 RH TAILGATE LOGO	130.00	1 PC	R ₁ 130.00	✓
17 RH TAILGATE EMBLEM (MULTIJET)	50.00	1 PC	R ₁ 50.00	✓
18 RH TAILGATE GLASS	490.00	1 PC	490.00	✓
19 RH TAILGATE INNER LOCK	370.00	1 PC	T ₁ 370.00	✓
20 RH TAILGATE INNER RUBBER	210.00	1 PC	210.00	✓
21 RH TAILGATE INNER BOARD	120.00	1 PC	D ₁ 120.00	✓
22 REAR END PANEL OUTER	400.00	1 PC	400.00	✓
			8,870.00	
Less 10%			887.00	7,983.00
Special Net				
23 LH TAILGATE GLASS GUM	30.00	1 PC	R ₁ 30.00	✓
24 RH TAILGATE GLASS GUM	30.00	1 PC	R ₁ 30.00	✓
25 STICKER - 70KM/H	10.00	1 PC	R ₁ 10.00	✓
26 STICKER - 3 PAX	10.00	1 PC	R ₁ 10.00	✓
27 REVERSE SENSOR	200.00	1 SET	D ₁ 200.00	✓
			280.00	280.00
Labour				
28 REMOVE & REFIX LEFT & RIGHT TAILGATE GLASS	160.00	1 LA	160.00	1402

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 28/09/2021
TP Veh Reg No: GBL1338H

Estimate No: ES2190921/YISHUN
Date: 29 Sep 2021
Policy No: Z/21/VC00/110925
Veh Reg No: GBB5249H
Make/Model: FIAT FIORINO 1.3MJTD
(225.2L20)
Chassis No: ZFA22500000059447
Engine No: 199A20003053439
Reg. Date: 27/05/2009

Estimate Repair Cost to Vehicle No :GBB5249H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
29 REMOVE & REFIX TAILGATES,REAR BUMPER ASSY,REAR LOCK ASSY,REAR WIPER,CUT,WELD & RENEW REAR END PANEL OUTER,KNOCK & REPAIR REAR END FLOOR BOARD PANEL,LH SIDE PANEL CORNAL & REALIGN THE SAME	1,000.00	1 LA	1,000.00	800
30 REMOVE & REFIX REAR GARNISH, TOP ROOF LINING,CARPET,ETC	120.00	1 LA	120.00	100
31 PUTTY & RESPRAY ON REAR LH SIDE PANEL,REAR FLOOR BOARD PANEL,REAR END PANEL,TAILGATES	1,000.00	1 LA	1,000.00	900
32 RUSTPROOFING	90.00	1 LA	90.00	✓
			2,370.00	2,370.00

Total S\$ 10,633.00

Add GST @ 7% 744.31

Total Amount Payable S\$ 11,377.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/09/2021 17:52 (SGT)
Date of Accident 28/09/2021 09:40 (SGT)
Exact Location of Accident Singapore
Additional Location Information TPE TOWARDS TAMPINES NEAR LAMP POST 527
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB5249H

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner OR KIM PEOW CONTRACTORS (PRIVATE)LIMITED
Company Reg No 1XXXXX891R
Email Address annieyeo@okph.com
Mobile Phone No (Phone) +65-63671960
Alternative Phone No (Office) +65-63671960

VEHICLE PARTICULARS

Manufacturer Fiat
Model FIORINO 1.3MJTD (225.2L20)
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 1248


INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Type of Coverage ThirdPartyFireTheft
Fleet Policy No
Policy Number Z/21/VC00/110925
Cover Note Number 27/5/21-26/5/22

DRIVER

Name of Driver KEE NAM ENG(JI NANYING)
NRIC No SXXXX426G

Sketch Plan



A: GBB5249H

B: GBL1338H

Malcom Ng IC: S9830688I
hp: 86112565

C: GBA 4956L
Ah-huat
hp: 98399985

D: GBK 6276A

E: GBD 7146Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA: 28/9/21

TIME: 0940hrs

Refer to police report: T/20210928/2045

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

() Claim Own Policy (X) Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

28/9/21
(45)