

ASS. REQ. BY:

Steve

VEH

CC4/L/PC21019110/ES3

ASSIGNMENT

From:

Date:

Veh No:

XD 93365

Yr Regn:

7/7/14

Estimated Cost:

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Tractor or

To Inspect Vehicle Not

Make:

ISUZU FX277M

c.2 9839

at Workshop m/s

Colour:

White

A/C: Insured / Std / NI / N

of

Sp. Reading

618038

T/Radio: Insured / Std / NI / N

Insured:

Eng/No:

Policy No.

C/No:

JALEX277 NIE 7000078

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Locked / Burnt or

(Client's Record)

Brake: In order / Jammed / Locked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:


F: 295/8R225

R:

11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Ret. or Market Value:

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

4 mm

R/Bal.

4 mm

SIA / PR Seen:

Consistent? : Yes or No

U/Bal.

4 mm

U/Bal.

4 mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

3/9/21

V-Fix

D.O.A.

29/9/21

Cum Sum:

%

3 Val.: Yes or No

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

Rear RH

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / CHASSIS frame / Body Structure affected due to collision

Date / Time Action / Instruction

MK-70K

Time/Time, File, Pass to:



: Prel. Report

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Time/Time, File Return to:



: Final Report

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$



: Weekend (\$

Transportation

S. & M. St

Photos

Quoted

TOTAL

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	394R
Vehicle Details	
Vehicle No.:	XD9336S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Sep 2021
Vehicle Make:	ISUZU
Vehicle Model:	FXZ77M
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	6UZ1486390
Chassis No.:	JALFXZ77ME7000078
Maximum Power Output:	-
Open Market Value:	\$80,504.00
Original Registration Date:	07 Jul 2014
First Registration Date:	07 Jul 2014
Transfer Count:	1
Actual ARF Paid:	\$4,026.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jul 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,001.00
COE Rebate Amount:	\$11,906.00
Total Rebate Amount:	\$11,906.00

The information contained herein is correct as at 29 Sep 2021

OK