

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Mr
PNG
HUAT WENG
145 LORONG AH SOO
#06-139
Singapore 530145

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

29-09-2021
5211043795
201009404M
30001
2021037049/ 1
29-09-2021
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLN1702K	3G24JZ	25-04-2017	WVWZZZ3CZHE055321	Passat Comfortline 1.8 TSI 132kW DSG	80,564

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B001	TO ALIGN LED HEADLIGHT (photo)				#1	100.00	107.00
3G0807217K GRU	Cover For Bumper Primed	1	pcs.	1,675.01	#1	1,675.01	1,792.26
3G0805903E 9B9	Spoiler Satin Black	1	pcs.	259.96	#1	259.96	278.16
3G0807889	Guide Piece	1	pcs.	93.24	#1	93.24	99.77
	BUMPER CTR BRACKET	1	pcs.		#1		
3G0807178	Guide Piece	1	pcs.	34.22	#1	34.22	36.62
	BUMPER INNER BRACKET RH	1	pcs.		#1		
3G0807050	Guide Piece	1	pcs.	43.45	#1	43.45	46.49
	BUMPER SIDE BRACKET RH	1	pcs.		#1		
3G0807251	Foam Insert	1	pcs.	116.84	#1	116.84	125.02
3G0998493	1 Set Sensor Brackets	1	pcs.	45.72	#1	45.72	48.92
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	81.16	#1	81.16	86.84
D 822150A1	Bonding Agent For Plastic	1	pcs.	65.18	#1	65.18	69.74
3G0853651A BKZ	Radiator Grille Satin Bla	1	pcs.	603.62	#1	603.62	645.87
3G0853671 9B9	Vent Grille With Satin Bl	1	pcs.	219.22	#1	219.22	234.57
	BUMPER CTR BRACKET	1	pcs.		#1		
3G0854662 9B9	Cooling Air Grill Satin B	1	pcs.	108.71	#1	108.71	116.32
	RHS FOG LAMP GRILLE	1	pcs.		#1		
3G0853254 2ZZ	Decorative Moulding Brigh	1	pcs.	92.85	#1	92.85	99.35
	RHS BUMPER LOWER MLDG CHROM	1	pcs.		#1		
3G2941114A	Led Headlight	1	pcs.	2,472.01	#1	2,472.01	2,645.05
	RHS LED H/LAMP	1	pcs.		#1		
3G0941120A	Gasket	1	pcs.	11.45	#1	11.45	12.25
3G0941120B	Trim Cover	1	pcs.	37.91	#1	37.91	40.56
	RHS H/LAMP TOP CHROM	1	pcs.		#1		
3G0941662L	Halogen Fog Lights With S	1	pcs.	330.64	#1	330.64	353.78
	RHS FOG LAMP	1	pcs.		#1		
3G0821022B	Fender	1	pcs.	755.26	#1	755.26	808.13
3G0821142A	Bracket	1	pcs.	59.75	#1	59.75	63.93
	RHS FENDER BRACKET	1	pcs.		#1		
3G0805970F	Wheelhouse Liner	1	pcs.	182.10	#1	182.10	194.85
	RHS FENDER LINER (UPPER)	1	pcs.		#1		
3G0805912T	Radhausschale-Kunststoff	1	pcs.	135.76	#1	135.76	145.26
	RHS FENDER LINER (LOWER)	1	pcs.		#1		
	LABOUR	42	pcs.	840.00	#1	3,360.00	3,595.20
	SPRAY PAINT	42	pcs.	800.00	#1	3,200.00	3,424.00
	AIG DIRECT SETTLEMENT						
	DOA: 28/09/2021						
	TP VEH: GBG6874U						
	SURVEY BY:						

Quotation valid till 06-10-2021

VW WAGEN CENTRE SINGAPORE

Andra Road
 Singapore 159934
 Reg. No.: 199101494Z
 ST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
 AIG ASIA PACIFIC INSURANCE P/L
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120

Customer Details:
 Mr
 PNG
 HUAT WENG
 145 LORONG AH SOO
 #06-139
 Singapore 530145

Document no.
 Document date 29-09-2021
 Customer no. 5211043795
 Customer GST-ID 201009404M
 Dealer 30001
 Job order number 2021037049/ 1
 Job order date 29-09-2021
 Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLN1702K	3G24JZ	25-04-2017	WVWZZZ3CZHE055321	Passat Comfortline 1.8 TSI 132kW DSG	80,564

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	860.00	13,984.06	7%	1,039.08	14,844.06	15,883.14
Total	860.00	13,984.06		1,039.08	14,844.06	15,883.14

*Steve (LKK)
 1/10/21, 10.00am*

*Wil Bel
 4 dyl
 P/P*

Customer

Service Advisor

My Bel smy

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: