

ASS. REC. BY:

REF:

AIG / 21070115/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SAMP 71460

Yr Regn:

10, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Prime Mover /

Truck / Traller or

Make:

Toy Altis

c.c

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

121292

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053 REH 60 4398821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Girlander 205/55R16

R:

Dm

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

3

mm

L/Bal.

8

mm

L/Bal.

3

mm

D.O.A.

26/8/21

D.O.I.

28/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s body & N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/10 @ 8:00.83 Car

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$