

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

DATE: 17-Sep-21

INSURANCE: China Taiping CP/P)

MODEL: Toyota Prius

MVA: LIM T S

VEHICLE NO.: SHD4784D

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$458.60
	Rear Bumper Re-Inforcement	1		\$318.80
	Rear Bumper Lower Cover-Black	1		\$552.60
	Rear Bumper Side Retainer RH	1		\$112.70
	Rear bumper Reflector RH	1		\$55.00
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Tow Cover	1		\$82.70
	SUB TOTAL			\$1,602.40
	LESS 25%			\$400.60
	DISCOUNTED TOTAL			\$1,201.80
	Reverse Sensor	1		\$135.70
	Rear Bumper Mat	1		\$50.00
	NETT TOTAL			\$185.70
	TOTAL SPARE PARTS			\$1,387.50
	Labour Charge			
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,207.50

DEF
?
DEF
?
CRK
NEC
MIS

X SVL
NEC

350
250
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
17/9/2021 1700
PIP
2 DAYS
CHECK ITEM PHOTO
BY LAWT PHOTO

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 17.09.2021 15:58

Page : 1

ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO305487344

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO: **SHD4784D**

MILEAGE

MAKE: **TOYOTA**

FUEL

MODEL: **PRIUS HYBRID(G4A17.09.2021 13:45**

E.....1/2.....F

YR OF MANU: **15.02.2020**

DATE/TIME IN

CHASSIS CODE: **JTDKB3FU203091124**

TARGET DATE

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 16.09.2021
Time: 3P 16.09.2021/C

NO

LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

Vehicle No.:

SHD4784D

SHD4784D

LIMITS

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard