

Not Withheld
Heavy B4 parts

83150.20 4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SMA 2026 D
MAKE : MERCEDES BENZ
MODEL : GLC250 4MATIC AUTO
YEAR : 2018
CHASSIS NO : WDC2539462F408454

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 29-Sep-21
DATE OF ACCIDENT : 24-Sep-21
THIRD PARTY REF : SHB 1728 Y
THIRD PARTY REF : SMRT Claims and Insurance Agency

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	o/s front door	Nett		\$ 2,214.00	
1pc	o/s front door rubbler	Nett		\$ 264.00	
	Less 10%			\$ 2,478.00	
				\$ 247.80	
				\$ 2,230.20	
2ks	RT door sticker 8120.001N MC				
	To putty & spray paint			\$ 600.00	
	To transfer door fitting			\$ 80.00	
	labour charges			\$ 400.00	
TG/VL	TOTAL			\$ 3,310.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: