

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305488937 Via Fax : EMISU
Date : 01-10-21 Your Insured : SMA 101X
Time of Fax : _____ Date of Acc : 01-10-21

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C 253FU

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdege.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

Date/Time: 01.10.2021 11:56

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4125589

JC NO305488937

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


JUNT CARD NO.

REGN NO: SHC2537U	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 01.10.2021 09:55
YR OF MANU. 13.12.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098658	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 01.10.2021
NATURE: 3P.01.10.2021

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to.: SHC2537U

JU AIG

Vehicle No.:

SHC2537U

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard


INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SMH101X

Date of Accident

01/10/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance **AIG Asia Pacific Insurance Pte....**

Period of Insurance **18/01/2021 - 17/01/2022**

Requested By **Por Moy Juan (COMFORTDELG...**

Requested Date **01/10/2021 10:41**

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Snc 2074

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305488937
 REGN NO : SHC2537U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.12.2017
 DATE/TIME IN : 01.10.2021 09:55
 ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,256.40	20.00	1,805.12
0002 04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,201.10	20.00	1,760.88
0003 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	2.00-	75.00
0004 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00

SUB-TOTAL : 3,721.00

JOB NATURE

0000 PB	PANEL BEATING	700.00
0001 SP	SPRAYPAINT CHARGE	800.00
0002 20-05	RENEW ADVERTISMENT STICKER-DOOR	200.00
0003 20-05	RENEW ADVERTISMENT STICKER-ROCKER	50.00
0004 L	TRANSFER DOOR PARTS	240.00

SUB-TOTAL : 1,990.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305488937
REGN NO : SHC2537U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 01.10.2021 09:5
ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,711.00

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO