

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 01.10.2021

Time: 12:06:57

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305488937
 REGN NO : SHC2537U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.12.2017
 DATE/TIME IN : 01.10.2021 09:55
 ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0593-G	PANEL ASSY-FR DR LH#	1	2,256.40	20.00	1,805.12	= } Bue
0002 04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,201.10	20.00	1,760.88	
0003 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	2.00-	75.00	= } etc.
0004 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00	

SUB-TOTAL : 3,721.00 ✓

JOB NATURE

0000 PB	PANEL BEATING	700.00	280
0001 SP	SPRAYPAINT CHARGE	800.00	50 700
0002 20-05	RENEW ADVERTISEMENT STICKER-DOOR	200.00	= } etc.
0003 20-05	RENEW ADVERTISEMENT STICKER-ROCKER	50.00	
0004 L	TRANSFER DOOR PARTS	240.00	120

SUB-TOTAL : 1,990.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305488937
REGN NO : SHC2537U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 01.10.2021 09:5
ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,711.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

4 Days.

45

After repair photos.

Gino Ai op

1/10/21

5071

-20%: 4050

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: