

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                           |                                                                                              |                 |                          |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-----------------|--------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                                  |                                                                                              |                 |                          |  |
| SOMPO INSURANCE SINGAPORE PL                                                                                                              |                                                                                              |                 | Ref: CS/SMO21010186/Avf3 |  |
| 50 RAFFLES PLACE #03-03                                                                                                                   |                                                                                              |                 | Date: 04/10/2021         |  |
| SINGAPORE LAND TOWERS SINGAPORE 048623                                                                                                    |                                                                                              |                 | Code: SMO                |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                              |                 |                          |  |
| Insured Veh.                                                                                                                              | SLA 521R                                                                                     | Veh. Inspected  | SLB 5499J                |  |
| Policy No.                                                                                                                                |                                                                                              | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                                 | CMTD2102948/SYH                                                                              | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                               | GRACE TEO                                                                                    | Assign Date     | 04/10/2021               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                              |                 |                          |  |
| Make & Model                                                                                                                              |                                                                                              | c.c             | 0                        |  |
| Engine No.                                                                                                                                | HIDDEN                                                                                       | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                               |                                                                                              | Colour          |                          |  |
| Odometer                                                                                                                                  | -                                                                                            | Steering        |                          |  |
| Brakes                                                                                                                                    |                                                                                              | Modification    |                          |  |
| General                                                                                                                                   |                                                                                              |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                              |                 |                          |  |
|                                                                                                                                           | Size                                                                                         | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                            |                                                                                              |                 | mm                       |  |
| L/H Front Tyre                                                                                                                            |                                                                                              |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                             |                                                                                              |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                             |                                                                                              |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                              |                 |                          |  |
|                                                                                                                                           |                                                                                              |                 |                          |  |
| <b>5. General Information</b>                                                                                                             |                                                                                              |                 |                          |  |
| Accident Date                                                                                                                             | 01/10/2021                                                                                   | Inspection Date | 04/10/2021               |  |
| Survey held at                                                                                                                            | RYDER AUTO PTE LTD<br>2 KAKI BUKIT AVE 2<br>#02-19/22 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                              |                 |                          |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                              |                 |                          |  |