

ASSIGNMENT

From:

Date:

Veh No:

Yr Regn:

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. SNM21D205614/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

\$8500

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LTA 3166

05/10/21 @ 5.06pm revised to Jacqueline Tan via Merimen.

F8Q7277J

03/11/19

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIT / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) __ \$ + RS __ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

) Site Insp (\$

) Interview (\$

) Tech. Invs (\$

) Weekend (\$

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288X
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 39237

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

ATTN: MOTOR CLAIMS DEPT

DATE : 02/10/2021
CLAIM NO. : 11802
POLICY NO. : V0107634-VMF
FROM : RAYMOND

VEHICLE NO. : FBQ7277J
MAKE/MODEL : /

*not Afford
due
the job. After 14 days
3 days
4/10/21
1/12/21*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount	
1	CHAIN BOX (STAINLESS STEEL) 2MM P/N: 24196 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	11	10.00 X
2	HOOK HOLDER (S/STEEL) P/N: 38796 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$6.50	11	26.00 X
3	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	2.00	\$63.00	125	126.00
4	REPAIR ON REAR BOX - (REPORTED BY MECHANIC)	Repair	1.00	\$84.00		84.00 ✓
5	RUBBER SEAL REAR BOX P/N: 70378 - (REPORTED BY MECHANIC)	REPLACE	80.00	\$1.00	?	80.00
6	SPRAY PAINT ON REAR BOX - (REPORTED BY MECHANIC)	Spray	1.00	\$260.00	250	260.00
7	STICKER (SINGAPORE POST) BOX REAR P/N: 39656 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	100	70.00 ✓
8	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH	Supply/Install	1.00	\$90.00	11 X	90.00

LIK Auto Consultants hence notify
the Repairer of the following:
• To resurvey **SUB TOTAL** painting
• To display **GST @ 7 %** during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bigSAFE



CERT NO: 22014-0393
ISO 9001:2015

*39237 *

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL (SGD)					\$798.22

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39237 *

bizSAFE₃



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	623M
Vehicle Details	
Vehicle No.:	FBQ7277J
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2021
Vehicle Make:	KYMCO
Vehicle Model:	SUPER JOCKEY 150I
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	SJ301000165
Chassis No.:	RFBSJ30GAK1000144
Maximum Power Output:	-
Open Market Value:	\$2,076.00
Original Registration Date:	03 Dec 2019
First Registration Date:	03 Dec 2019
Transfer Count:	1
Actual ARF Paid:	\$312.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Dec 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,889.00
COE Rebate Amount:	\$3,166.00
Total Rebate Amount:	\$3,166.00

The Information contained herein is correct as at 04 Oct 2021

OK