

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SHC 4699Y Veh. Inspected SMG 7694K	02/Euce2	
E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- THIRD PARTY CLAIM		
1. Policy Particulars :- THIRD PARTY CLAIM		
Insured Veh. SHC 4699Y Veh. Inspected SMG 7694K		
Policy No. Coverage (\$) 0.00		
Claim No. TAX/08/21/2051 Excess (\$) 0.00		
Assign From HUA YEN Assign Date 04/10/2021		
2. Vehicle Particulars & Condition		
Make & Model SKODA OCTAVIA c.c 999		
Engine No. HIDDEN Year of Reg. 2018		
Chassis No. TMBBP7NE3J0371754 Colour SILVER		
Odometer 37282 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 225/45 R17 BRIDGESTONE 4 mm		
L/H Front Tyre 225/45 R17 BRIDGESTONE 4 mm		
R/H Rear Tyre 225/45 R17 BRIDGESTONE 4 mm		
L/H Rear Tyre 225/45 R17 BRIDGESTONE 4 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 21/08/2021 Inspection Date 08/10/2021		
Survey held at VOLKSWAGEN GROUP SINGAPORE PTE LTD		
247 ALEXANDRA ROAD SINGAPORE 159934		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days		