

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Steve (LKK)
5/10/21, 11.30am

WNL RL
P/P
M BL M
3 dji

Quotation Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
GENEVIEVE
CHIN SHU WUN
MRS GENEVIEVE ZHANG
954 DUNEARN ROAD #08-13
SINGAPORE 589483

Document no. 01-10-2021
Document date 5211000972
Customer no. 198703792K
Customer GST-ID 30001
Dealer 2021037430/ 1
Job order number 01-10-2021
Job order date YEN MEI WONG
Service Advisor

License plate	Model code	First registration	VIN	Model	Mileage
SNB7740A	5T14NZR0	14-09-2021	VWGZZZ1TZW027147	Touran R-Line 1.4 TSI 110kW no.SR	17

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5TA833055AL	Door LHS REAR DOOR	1	pcs.	2,436.42	#1	1,754.22	1,877.02
5TA839701E 5AP	Door Seal Outer Black	1	pcs.	219.54	#1	158.07	169.13
D 378500A2	Sound Absorber Laminated	1	pcs.	43.65	#1	31.43	33.63
N 91203801	DOOR INSULATOR				#1	7.44	7.96
5TA839475G VNH	Bolt With Polygon Socket	2	pcs.	5.17	#1	109.73	117.41
	Window Slot Seal With Bla				#1		
	LHR DOOR GLASS OUTER MLDG (CHROM)				#1		
5TA839901A 041	Trim For Door Window Fram	1	pcs.	110.48	#1	79.55	85.12
	LHR DOOR TRIM (BLACK)				#1		
WHT005504	Fill. Hd. Screw	2	pcs.	2.76	#1	3.97	4.25
	LABOUR	31	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	31	pcs.	800.00	#1	2,400.00	2,568.00
	TRANSFER DOOR MECHANISM	1/2	pcs.	840.00	#1	840.00	898.80
	AXA ARF VS INDIA						
	3RD PARTY VEHICLE GBD8719M						
	D.O.A: 01-10-2021						
	SURVEY BY:						

Quotation valid till 08-10-2021

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,904.41	833.94	7%	606.51	833.94	8,664.41	9,270.92
Total	760.00	7,904.41	833.94		606.51	833.94	8,664.41	9,270.92

Customer

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VOLKSWAGEN
GROUP
SINGAPORE

Service Advisor