


REC BY: Thuan

TMI CS/TMI21010247/Vuf3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐  
To Inspect Vehicle No: SH 7921D  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: SNC 3388E  
Policy No. MQ000087  
Claims No. M2104625  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 2 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SH 7921D ✓ Yr Regn: 2811/21  
Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Hyundai Wnig c.c 1580  
Colour: blue A/C: Insured / Std / NI / NA  
Sp. Reading: 100423 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: km+1C85/CULU/42/35  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 195/65R15  
R: 195/65R15  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or westlake  
Front R/Bal. 5 mm Rear R/Bal. 5 mm  
L/Bal. 5 mm L/Bal. 5 mm  
D.O.A. 4/10/21 D.O.I. 4/10/21 1630  
Survey held at Comfort  
Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rebate: 3/563</u>

Confirmed P/P \$1998, 2 repair days.

(RED \$739.44; 27%)

Date/Time, File Pass to? ☐ : Prelim. Report15/10 TYPIST ☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 2Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

Total

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Wheel end (\$)Request Frm: TPRequest Sum: \$1998

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

821R

### Vehicle Details

Vehicle No.:

SH7921D

Vehicle to be Exported:

No

Intended Deregistration Date:

11 Oct 2021

Vehicle Make:

HYUNDAI

Vehicle Model:

AE IONIQ HEV FL 1.6 DCT

Primary Colour:

Blue

Manufacturing Year:

2019

Engine No.:

G4LEKU417510

Chassis No.:

KMHC851CVLU192135

Maximum Power Output:

103.6 kW (138 bhp)

Open Market Value:

\$24,602.00

Original Registration Date:

28 Jan 2021

First Registration Date:

28 Jan 2021

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Jan 2029

PARF Rebate Amount:

\$3,750.00

### Intended COE Rebate Details

COE Expiry Date:

27 Jan 2029

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$30,510.00

COE Rebate Amount:

\$27,813.00

**Total Rebate Amount:**

**\$31,563.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Oct 2021

OK



## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

*Jumani C/P*

Singapore

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/10/2021
Vehicle Reg. No.:	SH7921D	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	28/01/2021
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU417510	Chassis No:	KMHC851CVLU192135
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

### COST OF CLAIMS

	Amount
Parts	1,596.44
Miscellaneous Items	11.00
Labour	1,130.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,737.44</b>
<b>+ GST 7.00% (S\$)</b>	<b>191.62</b>
<b>Nett Amount (S\$)</b>	<b>2,929.06</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 04 Oct 2021)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11 ✓

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	*459.40 FL ✓/cut
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL ✓/scr
3	1		*REAR BUMPER BEAM	20.00	0.00	*394.80 FL ✓?
4	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL ✓nec
5	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	*155.00 FL ✓PDS
6	1		*REAR FOG LAMP	20.00	0.00	*201.50 FL ✓SVC
7	1		*ANTENNA - SMARTKEY	20.00	0.00	*40.50 FL ✓SVC
8	1		*REAR NUMBER PLATE	0.00	0.00	*50.00 F ✓cra
9	1		*BOOTLID EMBLEM - H	20.00	0.00	*28.00 FL ✓nec
10	1		*BOOTLID EMBLEM - IONIQ	20.00	0.00	*31.30 FL ✓nec
11	1		*BOOTLID EMBLEM - HYBRID	20.00	0.00	*24.30 FL ✓nec
12	1		*BOOTLID COMFORT LOGO	0.00	0.00	*30.00 F ✓nec
13	1		*BOOTLID TEL.NOS. LOGO	0.00	0.00	*30.00 F ✓nec
14	1		*BOOTLID APPS LOGO	0.00	0.00	*40.00 F ✓nec
Sub Total (S\$)						1,958.05
- List Item Discount on L Items (S\$)						361.61
Total Parts (S\$)						1,596.44

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00 ✓

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

400.00 350

2 SPRAYPAINT

New

600.00 500

3 CHECK WIRING

New

50.00 20

4 REMOVE/REFIX REVERSE SENSOR

New

80.00 30

Gross Labour Cost (\$\$)

1,130.00

ComfortDelGro Engineering Pte Ltd/SH7921D/04/10/2021 12:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Thuan@LkhAuto.com

82235769

4/10/19 1630

P/P bfr paint photo

wp 2clays

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	04/10/2021 13:30 (SGT)
Date of Accident	04/10/2021 09:00 (SGT)
Exact Location of Accident	Bukit Batok West Ave 6, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7921D
-----------------------------	---------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-93618307
Alternative Phone No	(Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

### DRIVER

Name of Driver	NG NGIAP CHENG
NRIC No	SXXXX341D

Occupation	Outdoor
Date Of Driving Pass	12/11/1966
Driving experience	54 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93618307
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 267B COMPASSVALE LINK #06-63
Address complement	-
Postcode	542267
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF DRIVER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON 04/10/2021 AT ABOUT 09:00HRS. I WAS DRIVING VEHICLE A, (SH7921D) TRAVELLING ALONG BUKIT BATOK WEST AVE 1 AT THE MOST LEFT LANE. I ENTERED INTO THE SLIP ROAD AND I STOPPED BEHIND THE GIVE WAY DOUBLE WHITE LINE GOING TOWARDS BUKIT BATOK WEST AVE 6. I WAS CHECKING FOR TRAFFIC COMING FROM MY RIGHT. SUDDENLY I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNC3388E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1



SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A-8H7924D  
B-SNC3388E

## Describe Circumstances of the Accident

ON 04/10/2021 AT ABOUT 09:00HRS. I WAS DRIVING VEHICLE A, SH7921D TRAVELLING ALONG BUKIT BATOK WEST AVE 1 AT THE MOST LEFT LANE. I ENTERED INTO THE SLIP ROAD AND I STOPPED BEHIND THE GIVE WAY DOUBLE WHITE LINE GOING TOWARDS BUKIT BATOK WEST AVE 6. I WAS CHECKING FOR TRAFFIC COMING FROM MY RIGHT. SUDDENLY I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE.

## Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time 10:55 04.10.21

Witnessed by Reporting Centre  
Personnel MD NARRIN



## INSURER ENQUIRY

Find  
insurer

Vehicle reg. no.

SNC3388E

Date of Accident

04/10/2021 

Reset

## % RESULT &amp; RECEIPT

## TP Insurer Enquiry

Insurance ..... **Tokio Marine Insurance Singa...**  
Period of Insurance ..... **20/01/2021 - 19/01/2022**  
Requested By ..... **Janet Lim Siang Gek (COMFOR...**  
Requested Date ..... **04/10/2021 11:21**

## Payment details

Request Amount: **S\$1.87**  
GST Amount: **S\$0.13**  
Total Amount Due (GST Inclusive): **S\$2**

## General Insurance Association

Records Management Centre  
GST Registration No: **M400017735**



Date/Time: 04.10.2021 11:47

Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4125818

JC NO 305489207

OMER

S

OMER NO

ESS

(R)

(P)

OUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD  
7010045  
383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

(O)

REGN NO:

SH 7921D

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 04.10.2021 10:05

YR OF MANU

28.01.2021

TARGET DATE

CHASSIS CODE

KMHC851CVLU192135

COMPLETION DATE/TIME:

### JOB DESCRIPTION


cident Date: 04.10.2021

TURE: 3P.04.10.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Jo.:

SH 7921D

JU TOKIO

Vehicle No.:

SH 7921D

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard