

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21010270/Utf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	13/10/2021	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKS 3767X	Veh. Inspected		SJK 3273H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011956/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		05/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH (A)	c.c		1794	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	JTDER12W403000763	Colour		GREY	
	Odometer	611608 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	PREMIO		6 mm	
	L/H Front Tyre	195/65 R15	PREMIO		6 mm	
	R/H Rear Tyre	195/65 R15	PREMIO		6 mm	
	L/H Rear Tyre	195/65 R15	PREMIO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/10/2021	Inspection Date		05/10/2021	
	Survey held at	LEE BROTHERS AUTOMOTIVE	PTE LTD			
		1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883				
5a.	<del>-</del>					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: