


Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Street Map showing Accident Location



Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Mo Guan – (Traffic Control , Signs, Barricades and Mini Excavator)

Affected Bus



Affected Bus



Mini Excavator

Affected Bus



Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Mo Guan – (Traffic Control , Signs, Barricades and Mini Excavator)



Remarks :

Operator need to swing outwards to avoid the Bus Stop Shether.

Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246


Subject : Public Bus – SG Love Bus – Tower Transit



Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Mo Guan – registered excavator operator



Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Mo Guan – Appointed Supervisor on site



Date : 28/09/2021

Location : Lim Chu Kang Road, Lp 246

Subject : Tower Transit - Bus Driver

