

Immediate Advice

To: AXA Insurance Pte Ltd

19/10/2021

Survey Details:

Date of loss	4-Oct-21
Date of appointment	6-Oct-21
Date of survey	6-Oct-21
Location of survey	YSK AUTO WORKSHOP

Vehicle Details:

Claim Type:	Third Party	y Claim	
Vehicle number	SKF 4985L	SKF 4985U	
Make and Model	HONDA O	DYSSEY 2.4L SUNROO	
Date of registration	7/6/2012		
Excess	-		
Market Value	\$	29,000.00	
Parf Rebate	\$	23,310.00	
Nett Loss	\$	5,690.00	

Repair details:

Initial Estimate	\$ 2,744.40

Proposed/Revised repair cost:

Parts	\$ 656.40
Check items (estimate)	\$ -
Labour	\$ 750.00
Total	\$ 1,406.40
Lump Sum(if applicable)	\$ 1,100.00

Number of days for repair	<u>3</u>



Remarks:

DAMAGES CONSISTENT.	

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	