



Your Ref: S1M03EV6

Date: 10th Feb 2022

Our Ref: CS3/ASM21008211/Gqy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01
Axa Tower
Singapore 068811
(The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBF 5367D
INSURED VEHICLE: GBA 2264M
ACCIDENT DATE: 31/07/2021**

We thank you for your instruction on 06/10/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBF 5367D from M/s Priority Services.
- b) Singapore Accident Statement of Vehicles GBF 5367D.
- c) Colour damaged vehicle photographs of GBF 5367D.

Pre-Repair Inspection Date: 04/08/2021 at M/s 39 Woodlands Close #01-34/35 Mega@Woodlands,
Repairer: Fa Autoworks Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF 5367D
Make & Model	: Toyota Dyna 3.0 Manual
Year of Registration	: 2016
Chassis Number	: KDY2318026359
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 13 (Thirteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.