

ASS. REC. BY:

REF:

072/ 21010313/kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT
Jennie

Veh No:

SKU 89196 Yr Regn: 08/15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Harrier c.c. 1986

Colour:

M Black AC: Insured / Std / NI / NA

Sp. Reading

104935 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ESU60 0049419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / RIM or

Tyre Size:

F:

R:

225/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The veh found damaged at the roof top.

The U/C / Chassis frame / Body Structure affected due to collision.

For witness & for O/S portion the cause of
damage due to fallen tree trunk.

Date / Time

Action / Instruction

7/10 Wksp Said I.B.I

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

NEXWAVE AUTO

**160 SINMING DRIVE
#05-15 SINMING AUTOCITY
SPORE :575722**

**ATTN
BILL TO
NUMBER PLATE
HP**

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
MOTOR CLAIMS DEPARTMENT
SKU8919G HARRIER
91384382 ✓

DATE _____

04-10-21

PREPARED BY :

JENNIE TAN

COMMENTS OR SPECIAL INSTRUCTIONS

THROUGHOUT DISMANTLING PROCESS ,ANY WEAR N TEAR PARTS MAY OCCUR
PRICES MAY VARY ,THANK YOU FOR UNDERSTANDING

Cost

[illegible]

THANK YOU FOR YOUR BUSINESS!

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Back to OneMotoring

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	593R
Vehicle Details	
Vehicle No.:	SKU8919G
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 CVT
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	3ZRB589314
Chassis No.:	ZSU600049419
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,033.00
Original Registration Date:	20 Aug 2015
First Registration Date:	20 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$23,447.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Aug 2025
PARF Rebate Amount:	\$15,240.00

Intended COE Rebate Details

COE Expiry Date:	19 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$23,498.00
Total Rebate Amount:	\$38,738.00

The information contained herein is correct as at 07 Oct 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/10/2021 15:42 (SGT)
Date of Accident 01/10/2021 17:00 (SGT)
Exact Location of Accident 240 Sime Rd, Singapore 288303
Additional Location Information SICC Sime Course Visitor Carpark
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKU8919G

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Heng Boon Seng Construction Pte Ltd
Company Reg No 198500593R
Email Address hbcs@singnet.com.sg
Mobile Phone No (Phone) +65-97354974
Alternative Phone No (Home) +65-97354974

VEHICLE PARTICULARS

Manufacturer Toyota
Model HARRIER ELEGANCE 2.0 CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Auto
CC 1986

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00156592104
Cover Note Number -

DRIVER

Name of Driver Heng Meng Kwang
NRIC No S1527284H