<b>ASSIG</b>	NMI	ENT

From: Date:	Veh No: SLV 7794M Yr Regn: 2018 1311
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD THIWS ITP RESIOD RESIEVA I INVIMV	Truck / Trailer or
To Inspect Vehicle No: SLV 7794M	Make: HYUNDAI GLANTRA HOILLISTE.C 1591
at Workshop m/s how (Name	Colour A/C: Insured / Std / NI / NA
of 6, majesicinh LN	Sp.Reading 21609 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KM 40841CM JU613240
Claims No.	Gen. Cond: Good / Fail / Poor / Burnt
Sum Insured: Excess: TBA	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
• • • • • • • • • • • • • • • • • • • •	Tyre Size: F: 265/85 R16
(Policy Condition)	
Remark: The veh had commenced its  N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 59K	TOYO/YOKO or Kunhtho
	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. 25/09/21 D.O.I. 58/16/21
•	10/10/10/
Lum Sum: % 3 Val.: Yes or No	Survey held at Auro Insult
Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS	1
Lum Sum: % 3 Val.: Yes or No	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted: Vehicle: IN / OUT	Survey held at Auro Insult
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  April   Nation   Date / Date / Date   Date / Dat	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.
Lum Sum:  % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  Days Of Repair:
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  Days Of Repair:  Resurvey No. of Trip:  Survey Fee:
Lum Sum:  % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time	Des. of Damages Frt Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:
Lum Sum:  % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ ):_S+RS,_SI
Lum Sum:  % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date:  Person Contacted:  Date / Time	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or  The U/C / Chassis frame / Body Structure affected due to collision.  Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ ):_S+RS_SI

# auto Insure Pte. Ltd 6 Marsiling Lane 739145

**Insurer Reference: SLU7794M** 

Repairer Reference: M3175 / SLU7794M Date calculated: 07/10/2021 10:48 AM



**Full Report** Registration: SLU7794M

Printed: 07/10/2021 10:49 AM

### **Summary Information**

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference:

Min Seng Chong **SLU7794M** 

Currency:

Date of Incident:

Hire Car Start: Hire Car End:

SGD 25/09/21

Estimated Repair Time: Actual Repair Days:

6 6

### **Vehicle Details**

**Vehicle** 

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration:

VIN number:

**HYUNDAI** 

ELANTRA (AD) BASE MODEL

30 92 01 SLU7794M

KMHD841CMJU613240

Odometer: 24609


# **Vehicle Condition**

# **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

## Damage Areas

All	2 -
Underbody	- 3



### **Tyres Condition**

Tyre Brand

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right

Condition

mm

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

#### Labour

	Time Base 10 WU/h	Price = 42	.00 SGD/h
Code	Description	WU	Price SGD
18600A00	ADJUST HEADLAMPS	3.0	12.60
NO NUMBER	R + R FRONT PANEL	16.0	67.20
86510R00	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, GRILLE AND NECESSARY ATTACHED PARTS	8.0	33.60
66400R00	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	7.0	29.40
79110R00)	R + R L/BONNET SEAL	1.0	4.20
79110R5A)	R + R R/BONNET HINGE	1.0	4.20
66300R00)	R + R L/F WING INCLUDES: R + R HEADLAMP AND NECESSARY ATTACHED PARTS DOES NOT INCLUDE: R + R FRONT BUMPER,	4.0	16.80
66300R5A)	ADJUST HEADLAMP R + R R/F WING INCLUDES: R + R HEADLAMP AND NECESSARY	4.0	16.80

code	Description			wu	Price SGD
	ATTACHED PARTS				
	DOES NOT INCLUDE: R + R FRONT BUM	PER,			
20100000	ADJUST HEADLAMP  R + R AIR CLEANER CPL			3.0	12.60
28100R00 25300R00)	R + R RADIATOR		We remain the	7.0	29.40
NO NUMBER				3.0	12.60
0741	L/F WING REPAIR	是我们在自己的,但是他的现象的概念是自己的。这个证明		5.0*	× 21.00
0742	R/F WING REPAIR		L. F. S. S. L. K. L. K. L.	5.0*	× 21.00
	Labour Cost		Hrs	WU	204 40
	Panel / Mechanical Labour		6.70	67.0	281.40
	Total of Labour				281.40
Paint					
Paint Work	SYSTEM	AZT	Tin	ne Basis	10 WU/h
Code	Description			WU	Price SGD
	BONNET NEW PART PAINTING	A CONTRACTOR OF THE PROPERTY O		21.0	
	FRONT BUMPER NEW PART PAINT K1R	* Annear Charles Ellistin Tomber Signature (1917) House		9.0	The second second second second
	L/F WING REPAIR PAINTING >50%			14.0	
	R/F WING REPAIR PAINTING >50%			14.0	
Paint Materi	ial Per Part				
Code	Description				Price SGD
0471	BONNET NEW PART PAINTING				56.82
0283	FRONT BUMPER NEW PART PAINT K1R	The state of the s			33.50
0741 0742	L/F WING REPAIR PAINTING >50%				10.27
0742	R/F WING REPAIR PAINTING >50%				10.27
	Labour Cost - Paint		Hrs	WU	Price SGD
	Factor	42.00 SGD/h			Trice Sup
	Time Paint			58.0	
	Preparation Main Work Metal		1.70	17.0	71.40
	Preparation Comp. Work Plastic <b>Total</b>		0.30	3.0	12.60
	Joen	10 WU/h	7.80	78.0	327.60
	Material Cost - Paint				
	New Part Painting				Price SGD
	New Part Painting - Plastic K1R				56.82
	Repair Painting				33.50
	Material constant Metal				20.54
	Material-constant Plastic <b>Total</b>				18.10 9.00
					137.96
Spare Par	ts				
Code	Description Part Numbe	or Dowl C	prices	as at 20	015-06-01
	· are Numbe	er Part Source			Price SGD

code	Description / P	art Number	Part Source	Price SGD
0471		5400F2000	Original	540.00
0492	BONNET LOCK X 8:	1130F2910	Original	90.00
0283	FRONT BUMPER * CASS	5510F2000	Original	265.00
0315	FRONT IMPACT DAMPER 86	5520F2000	Original	66.00
1009		4101F2000	Original	335.00
0341	FRT BUMPER REINF? 7 86	5571F2000	Original	48.00
0340	FRT BUMPER SUPPORT . 64	1900F2010 <b>,</b>	Original	265.00
0260	FRT NO PLATE REINFOR 86	5519F2000	Original	17.00
0410	GRILLE CM/ 86	350F2000	Original	540.00
0475	L/BONNET HINGE 7 79	9110F2000	Original	42.00
0321	I /F INN BUMPER BRKT . 86	553F2000	Original	22.00
0323	L/HEADLAMP REINF? 7 64	118F2000	Original	24.00
0561	LEFT HEADLAMP ASSY ' 92	2101F2030	Original	650.00
0476		120F2000	Original	42.00
0322	R/F INN BUMPER BRKT 86	554F2000	Original	22.00
0324	R/HEADLAMP REINF . 64	128F2000	Original	24.00
0412	RAD GRILLE BRACKET 286	356F2000	Original	66.00
0562	RIGHT HEADLAMP ASSY .92	102F2030	Original	650.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Addition(+10.00%)			0.00 3,708.00 370.80
	Total			4,078.80

## **Extras**

Code	Description	Price SGD
1000	NO PLATE & HOLDER FRONT 64/	
1001	BUMPER CLIPS FRONT	SO 60.00*
1002	AIR CON GAS FRONT	<i>3 o</i> 50:00*
1003	RADIATOR COOLANT FRONT	100.00*
1005	Total Extra	60.00*
	Total Extras	270.00

200				
einal	Ca	CII	lati	on
Eindi	Cu	-	-	

SGD	SGD
3,708.00	
	4,078.80
281.40	
	281.40
	270.00
227.60	
137.90	465.56
	405.50
	5,095.76
	356.70
	5,452.46
<b>500.00</b>	
-500.00	
	-500.00
	4,595.76
	321.70
	4,917.46
	7,517170
	3,708.00 370.80

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hp 90010068

Y days

L/S

OB/10/21@18W

EXCESS:TBA

REVENT

REM after repair

Page 5 of 5

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Data of Outrologica	07/00/0004 40 00 (OOT)
Date of Submission	27/09/2021 16:22 (SGT)
Date of Accident	25/09/2021 15:00 (SGT)
Exact Location of Accident	Ophir Rd, Singapore
Additional Location Information	· •
Country/State of Loss	Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number	***************************************	SLV7794M
-----------------------------	---	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TIANG SOO HUA
NRIC No	SXXXX483I
Email Address	PW8741@HOTMAIL.COM
Mobile Phone No	(Phone) +65-98271022
Alternative Phone No	+65-98271022

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Elantra
Variant	_ 30-
Exact purpose for which vehicle was being used at time of	
accident	Private use
Are you claiming under your own insurance policy for repair to	
your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

#### **INSURANCE COMPANY**

Name of Insurance Company Type of Coverage Fleet Policy Policy Number	China Taiping Insurance (Singapore) Pte. Ltd. Comprehensive No
Cover Note Number	DMPCSNW00197242000

#### DRIVER

Name of Driver NRIC No	TIANG SOO HUA
	SXXXX483I

Date Of Birth	30/12/1967
Occupation	Indoor
Date Of Driving Pass	07/04/1994
Driving experience	27 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98271022
Alt. Phone Number	+65-98271022
Email Address	PW8741@HOTMAIL.COM
Address	BLK 80 TANJONG RHU RD #07-03
Address complement	Annie Marie
Postcode	436892
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured  Does Driver Own Other Vehicles?	
Vehicle Registration Number of Other Vehicle Owned by Driver	No
venicle registration realists of other venicle owned by briven	
Insurance Company of Other Vehicle Owned by Driver	
The state of the s	AND THE RESIDENCE OF THE PARTY
GENERAL INFORMATION OF THE ACCIDENT	
The state of the s	TALLED THE SECOND CONTRACTOR OF THE SECOND CON
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
The state of the s	
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Soliciting/offering decident status electrons	
DETAILS OF POLICE ACTION	
A CONTROL OF THE CONT	CONTROL OF STATE OF S
Was the accident reported to the police?	No
Was notice of intended Prosecution given?  If yes, against whom?	No
if yes, against whom?	-
CIRCUMSTANCES OF ACCIDENT	
I WAS TRAVELING ALONG OPHIR RD GOING TO ECP, THE C	CAR IN FRONT SUDDENLY BRAKE. I CANNOT STOP IN TIME.
ATTACHMENT(C)	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No
DETAILS OF OTHE	R VEHICLE PROPERTY 1
Vohicle Registration Number	
Vehicle Registration Number Vehicle Manufacturer	SLD2656G
Vehicle Model	- -
Vehicle Variant	The second of th
Vehicle Colour	
Vehicle Category Name of Driver	Private car
Contact Number	
Address	
Address complement	

KETCH PLAN



### 中国太平保险(新加坡)有限公司

Mictor Private Car

MICH

N 521

CERTIFICATE OF INSURANCE

ldator Verticles (Tited-Perty Roses and Compensation) Ad (Chapter 189)
Motor Verticles (Tited-Perty Roses and Compensation) Roses, 1560
Rose Transport Act, 1987 (Malanysia)
Roser Verticles (Tited-Perty Black) Bales, 1500 (Malanysia)

ANDUAL Cov. Type:C

CERTIFICATE NO.

DMPCSNW00197242000

Engine No.: G4FGHU127649 Cha. No.: KMHD841CMJU613247

E. Frider Mark and Registration

SLVTTOAM

Number of Version

AUTOSAFE

2. Name of Policy Holder

TIANG SOO HUA

Named Drivers Ex Sect. 1 \$5500.00

18/01/2021

Additional Ex Other than Named Drivers:

881.000.00

1501/2022

Ex Sect. 1 - Age <+ 25 Ex Sect. 1 - Age >= 25 Age as at date of accident EX ON WINDSCREEN

5\$100.00

Persons or Classes of Persons sriched to drive\*
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the Scoreing or other laws or regulations to drive the Mobil Victorie or has been so permitted wild in not disqualited by order a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as \$5-104."

Like for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for him or neward subon driving best racing pace-making, reliability trul, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade

ver is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) Excess sunichever is applicable for losses occurring outside singapure (common the supplied of doubled.)
One first Walver of Excess for the first \$5500 will apply to the Insured and Named Orivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

\*Limitations rendered engerative by Section 6 of the Motor Vehicles (Third-Party Risks and Comprehension) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Mataysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

PORE) PTE. LTD. For CHINA TAIPING INSURANCE (S

tisued By: META AGENCY PTE LTD

Authorized Officer

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E)

13 Anson Road #16-00 Springles/Tower Singapore 079909

C63896111

**9**6222 1033

www.sg.cntaiping.com

	the second section of the second of the seco	Allert and the second second second second second					
					en elektrik en de en elektrik		
	3						
	112				1		march
	1-2		18			74-1	7794-1 26.56G
	3				B	SLO.	2636G
	10-	5		and the second s			
	11191	4					
ESCRIBE CIRCU	MSTANCES OF	THE ACCIDENT	y to		, in		
T WA	x tra	of in t	along	Ophir	RA	goin	e go
ECP -	the ca	Jeni v	us twa	ddenly	830	p br	cat.
TOOL	to tone	m in t	Evel.		7	*	
7 6.00	1410/ 311	4					
-			ale and			ange (Carlotte Carlotte Carlot	
the trade of the second							
4			The second secon				
			384				
							Assert for observed
						43.240.00	
						23200	
DECLARATI						1 1	
		ulars are true in eve	y respect.			A ha	
		ulars are true in eve	y respect.			Mar	
	the foregoing partic	Driver's Signa		Reg		A daring re-Personnel's	s Signature

GIARNE sketchPlanForm V3

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:		
Owner ID:	Singapore NRIC	
Vehicle Details	4831	
Vehicle No.:	SLV7794M	
Vehicle to be Exported:	No	
Intended Deregistration Date:	07 Oct 2021	
Vehicle Make:	HYUNDAI	
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)	
Primary Colour:	Silver	
Manufacturing Year:	2017	
Engine No.:	G4FGHU127649	
Chassis No.:	KMHD841CMJU613240	
Maximum Power Output:	93.8 kW (125 bhp)	
Open Market Value:	\$13,859.00	
Original Registration Date:	16 Jan 2018	
First Registration Date:	16 Jan 2018	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$13,859.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	15 Jan 2028	
PARF Rebate Amount: Intended COE Rebate Details	\$10,394.00	
COE Expiry Date:	15 Jan 2028	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$41,400.00	
COE Rebate Amount:	\$25,964.00	
Total Rebate Amount: The information contained herein is correct as at 07 Oct 2021	\$36,358.00	

ОК

# Hyundai Elantra 1.6A GLS S

Overview	Financial Accessories	Similar Research	h Photos Map
Price	\$59,800		
Depreciation (	\$8,530 /yr View models with similar de	Reg Date	08-Feb-2018 (6yrs 3mths 27days COE left)
Mileage	68,000 km (18.5k /yr)	Manufactured (*)	2018
Road Tax ①	\$738 /уг	Transmission	Auto
Dereg Value (	\$32,109 as of today (chang	e) OMV(?)	\$11,683
COE	\$36,890	ARF	\$11,683
Engine Cap	1,591 cc	Power	93.8 kW (125 bhp)
Curb Weight	1,345 kg	No. of Owners	
Type of <b>V</b> ehicl	e Mid-Sized Sedan		