

ASS. NO. 311

Steve 7

CS/401 21010549/E+13

ASSIGNMENT

From:

Date:

Veh No:

YQ 4213R

Yr Regn:

21/7/21

Estimated Cost:

OR TYPE / PRES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Online No.

Sum Insured:


Excess:

(Ollon's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

ICAO Accident Report

Consistent? : Yes or No

GA / PR Seat

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Sum Sum:

%

3 Vol.: Yes or No

QA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Hino XZU 110R

ct

4001

Color:

White

AJO:

Insured / Bid / NI / N

Sp. Reading

5280

TIRadio:

Insured / Bid / NI / N

Eng/No:

O/No:

XZU 110R hino VS

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

Pt

195R15C

Rt

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

U/Bal:

4

mm

U/Bal:

4

mm

D.O.A.

1/19/21

O.C.I.

8/19/21

Survey held at

Borapo Market

Des. of Damages

Front

Rear

O/S

NIS

UIC

Reclap or

The UIC / chassis frame / Body Structure affected due to collision

Date/Time

Action/Instruction

MV-92K

Confirm final PART value

Confirm final figure at \$16,030.10, 10 days.

RED: 4760.10:22%

me/Time, File, Report

☐

Prell. Report

☐

Final Report

me/Time, File, Report

Days Of Repair:

10

Resurvey No. of Trips

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Vehicle (\$

Survey Fee

Transportation

Food

Quota

Other

TOTAL

me/Time, File, Report

me/Time, File, Report



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no. 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1	M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064
	Document No. 0	
	Document Date 06/10/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	650D/YQ4213R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JHHUCV3F80K039474	N04CWN14777	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: DHOM120061422100 ACC DATE:01.10.21 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				220.00
4	S	BP-SUBLET RESET AND REPROGRAMME E CU.				220.00
5	S	BP-SUBLET REMOVE AND REINSTALL FRT DASH BOARD (photo) 880 x 2				1760.00
6	S	BP-SUBLET REMOVE AND REGAS AIR CON COMPONENTS TO ASSIST REPAIR.				880.00
7	S	BP-SUBLET REPLACE FRT WIRING HARDNESS ASSY.				880.00
8	S	BP-SUBLET CONDUCT WATER TEST.				220.00
9	S	BP-SUBLET REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, FRT PANEL ASSY, 880 x 3 FRT BUMPER AND INNER PANEL AND AFFECTED PORTION OF CAR.				2640 4400.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Indicape


Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc	S1000019 / ICUOI1 Document No. 0 Document Date 06/10/2021	M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	65OD/YQ4213R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JHHUCV3F80K039474	N04CWN14777	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET SPRAY PAINT ON FRT AFFECTED PORTION OF CAR. 3 x 660				1980 2640.00
11	1	H52111-37400 A0 BAR, FR BUMPER / BR	1.00	967.20		967.20
12	2	H52141-37222 STAY, FR BUMPER, RH / BR	1.00	306.00		306.00
13	3	H52142-37202 STAY, FR BUMPER, LH / BR	1.00	306.00		306.00
14	4	H52021-37022 REINFORCEMENT SUB-AS / BR	1.00	1116.20		1116.20
15	5	H52131-37111 REINFORCEMENT, FR BU / BR	1.00	62.00		62.00
16	6	H52136-37011 REINFORCEMENT, FR BU / BR	1.00	50.80		50.80
17	7	H81110-37751 HEADLAMP ASSY, RH X	1.00	1086.50		1086.50
18	8	H81150-37751 HEADLAMP ASSY, LH / BR	1.00	1086.50		1086.50
19	9	H55701-37070 FRT COWL CAB PANEL / BR	1.00	641.40		641.40
20	0	H53111-37B30 A0 GRILLE, RADIATOR / BR	1.00	701.30		701.30
21	1	H53142-37020 GARNISH, RADIATOR GRILLE, NO.2 / BR	1.00	256.50		256.50
22	2	H53143-37020 GARNISH, RADIATOR GRILLE, NO.3 / BR	1.00	44.20		44.20
23	3	H75315-37100 ORNAMENT, RADIATOR G / BR	1.00	76.50		76.50
24	4	H75311-37330 PLATE, FR NAME, NO.1 / BR	1.00	35.30		35.30
25	5	H75311-37320 PLATE, FR NAME, NO.1 / BR	1.00	37.80		37.80
26	6	H82114-37320 WIRE, ENGINE ROOM, NO.4 / BR	1.00	123.70		123.70
27	7	H52112-37130 EXTENSION, FR BUMPER / BR	1.00	43.70		43.70
28	8	H52113-37050 EXTENSION, FR BUMPER / BR	1.00	43.70		43.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due
			

Customer Copy

Inchicope

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building Singapore cc			S1000019 / ICUOI1		M/S Eksklusiv Landscape Pte Ltd 1 Bukit Batok Crescent #03-19 Singapore 658064			
			Document No. 0					
			Document Date 06/10/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2021	XZU710R	WKMMV3	21/07/2021	YQ4213R	0	10211	650D/YQ4213R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JHHUCV3F80K039474		N04CWN14777	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	9	H82121-37L90 WIRE, ENGINE ✓ BR			1.00	219.60		219.60
<div style="display: flex; justify-content: space-between;"> <div> <p><i>Steve (LKK)</i> 8/10/21, 10.00am</p> </div> <div> <p><i>OD-AL AL</i> <i>EXCISE-?</i> <i>P/P</i> <i>My Bel Sky</i> <i>10 dys</i></p> </div> </div> <div style="border: 1px solid blue; padding: 5px; margin-top: 10px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div>								
For & on behalf of		Acknowledged by Repairer		Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd		Date:		Please acknowledge receipt of vehicle		Parts 7,204.90 Labour 320.00 Sublet 11,080.00 Lubrication/Fluid 0.00 Others 0.00		18,604.90 GST 7.00% 1,302.34 Less 0.00 Amount Due 19,907.24

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/10/2021 14:00 (SGT)
Date of Accident	01/10/2021 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE OVER KALLANG EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YQ4213R

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	EXKLUSIVE LANDSCAPE
Company Reg No	1XXXXX152R
Email Address	SOLIMAN@EXKLUSIVELANDSCAPE.COM
Mobile Phone No	(Phone) +65-98901557
Alternative Phone No	(Office) +65-64811383

VEHICLE PARTICULARS

Manufacturer	Hino
Model	300
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3000

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DHOM120061422100
Cover Note Number	-

DRIVER

Name of Driver	PERUMAL SAMIKANNU
Passport No/FIN	GXXXX760T

Date Of Birth	09/01/1989
Occupation	Outdoor
Date Of Driving Pass	07/11/2018
Driving experience	2 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98901557
Alt. Phone Number	-
Email Address	SOLIMAN@EXKLUSIVELANDSCAPE.COM
Address	1 BUKIT BATOK CRESCENT #03-19 WCEGA PLAZA
Address complement	-
Postcode	658064
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC6643Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-92224120
Address	-
Address complement	-

Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
-
-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKY4768K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

4/10/21

Policyholder's Signature
Time 11:30 am

Sketch Plan



Sly

04/10/21 11:30

Driver's Signature (If driver is not the policyholder) / Date
& Time

Francis Cher

Motor Claims Assessor
Borneo Motors (S) Pte Ltd

Witnessed by Reporting Centre
Personnel




Describe Circumstances of the Accident


Accident Report : Attached.


Declaration

We declare the foregoing particulars are true in every respect.


04/10/21
Policyholder's Signature / Date
Time 11:30am




04/01/21 11:30
Driver's Signature (If driver is not the policyholder) / Date
& Time



Francis Cher
Motor Claims Assessor
Borneo Motors (S) Pte Ltd
Witnessed by Reporting Centre
Personnel

ACCIDENT REPORT

Location : PIE near Kallang Exit
Date/Time : 1st Oct 2021 / 12:30pm

I, Perumal Samikannu, driver of lorry YQ 4213R

Driving PIE towards TuoS and near Kallang Exit.
While I'm driving with normal speed and correct distance in front vehicle. Suddenly I noticed the 1st car (gray - SKY 4768K) immediately full-stop the 2nd car (white - SLC 6643Y) also full-stop and very closed to the 1st car (around 1 meter gap). I shocked and push my brake pedal for full-stop also, but still reached and hit the 2nd car, then the 2nd car because he (driver 2nd car) very closed to 1st car, he also hit the 1st car and make a minor damaged.


Perumal Samikannu

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DH0M120061422100	Excess:	\$500/-SECTION 1 \$100/-WINDSCREEN DAMAGE CLAIM \$3000/-APPL TO <25 YRS & OR <3YRS EXP
Type of Cover	COMPREHENSIVE		
Vehicle Number	YQ4213R		
Name of Insured	EXKLUSIVE LANDSCAPE PTE LTD		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 21 July 2021 to 20 July 2023
Hire Purchase UNITED OVERSEAS BANK LIMITED

Engine# N04CWN14777
Chassis# JHHUCV3F80K039474

MZ 801

AUTHORISED DRIVER

Any person provided he is in the Insured's employ and is driving on their order or with their permission

LIMITATIONS AS TO USE

Use in connection with the Insured's business
Whilst the Motor Vehicle is being so used the carriage of passengers is permitted
THE POLICY DOES NOT COVER
(1) Use for racing pace-making reliability trial or speed-testing
(2) Use for the carriage of passengers for hire or reward
(3) Use whilst drawing a greater number of trailer in all than is permitted by law


Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

FSGHY Date : 22/07/2021


For the Company

01 October 2021

To: Whom It May Concern

BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape Bodycare Centre

Level 4, Inchcape Centre, 2 Pandan Crescent, Singapore 128462

Dear Sir / Madam,

This is to authorize that our Driver, **Mr. PERUMAL SAMIKANNU (FIN No.: G8222760T)** to report on the incident or sent the vehicle YQ4213R to the workshop. Thank you.

Yours Sincerely,



Andrew Sze Ming Hwi

Managing Director