


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OR: TP / WS / PR / OD / RES / EVA / INV / MV
 To inspect Vehicle Not: _____
 at Workshop m/o: _____
 of: _____
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)
 Remarks: The vch had commenced its
 repair at the time of inspection.



Rel. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 DIA / PR. Seen _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Vch No: SLV 83635 Yr Regn: 18/1/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Text / Prime Mover /
 Truck / Trailer or
 Make: Lexus ES300H C.B. 1994
 Color: Silver A/O: Insured / Std / NI / N
 Sp. Reading: 157198 TIRadio: Insured / Std / NI / N
 Eng/No: _____
 C/Vo: THRW 14.6.4 218/753
 Gen. Cond: Good / Fair / Poor / Bupl
 Steering: In order / Jammed / Locked / Burnt or
 Brake: In order / Jammed / Locked / Burnt or
 Mod: NII / S/Rlm / STD A/Rlm or
 Tyre Size: F: 215/55ZR17
 R: _____
 BS / DUN / EXNÖVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or Nexen
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 11/1/21 D.O.A. 11/1/21
 Survey held at Borneo
 Des. of Damages: Fnt / Rear / O/S / N/S / U/G / Reclap or
Front RH
 The U/G or chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-179K

Time/Date, File, Report, _____
☐ : Prelim. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trips: _____

Survey Fee:

Transportation

\$ + RS. \$

Private

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inva (\$ _____)

☐ : Witness (\$ _____)

Special Form:

Comp Sum / L.P. / H.P.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	235H
Vehicle Details	
Vehicle No.:	SLV8363S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2021
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H EXECUTIVE CVT S/R
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2AR1878569
Chassis No.:	JTHBW1GG402181753
Maximum Power Output:	151.0 kW (202 bhp)
Open Market Value:	\$42,522.00
Original Registration Date:	18 Jan 2018
First Registration Date:	18 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$51,531.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2028
PARF Rebate Amount:	\$38,648.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$28,378.00
Total Rebate Amount:	\$67,026.00

The information contained herein is correct as at 11 Oct 2021

OK