

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/196-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI21010376/Kqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHC 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	27/10/2021	
				Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLK 6642H	Veh. Inspected		SHD 5427D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011967/HA	Excess (\$)		0.00	
	Assign From	CHRISTINA	Assign Date		08/10/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTDKB3FU903079181	Colour		M.P. WHITE / RED	
	Odometer	222510 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	SAILUN		8 mm	
	L/H Front Tyre	195/65 R15	SAILUN		8 mm	
	R/H Rear Tyre	195/65 R15	SAILUN		7 mm	
	L/H Rear Tyre	195/65 R15	SAILUN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/10/2021	Inspection Date	е	11/10/2021	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: