



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile          |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|------------------------------------------------------------|------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811 |                                                                                                                                                                                                                                                  |                                          | Ref: CS3/ASM21010403/Vvy3<br>Date: 11/10/2021<br>Code: ASM |            |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>                        |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            | Insured Veh.                                                                                                                                                                                                                                     | SH 9637L                                 | Veh. Inspected                                             | SLU 3048R  |
|                                                                            | Policy No.                                                                                                                                                                                                                                       |                                          | Coverage (\$)                                              | 0.00       |
|                                                                            | Claim No.                                                                                                                                                                                                                                        | S1M03JNX                                 | Excess (\$)                                                | 0.00       |
|                                                                            | Assign From                                                                                                                                                                                                                                      | LOH CYNTHIA                              | Assign Date                                                | 11/10/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                              |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            | Make & Model                                                                                                                                                                                                                                     |                                          | c.c                                                        | 0          |
|                                                                            | Engine No.                                                                                                                                                                                                                                       | HIDDEN                                   | Year of Reg.                                               |            |
|                                                                            | Chassis No.                                                                                                                                                                                                                                      |                                          | Colour                                                     |            |
|                                                                            | Odometer                                                                                                                                                                                                                                         | -                                        | Steering                                                   |            |
|                                                                            | Brakes                                                                                                                                                                                                                                           |                                          | Modification                                               |            |
|                                                                            | General                                                                                                                                                                                                                                          |                                          |                                                            |            |
| <b>3. Conditions of Tyres</b>                                              |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            |                                                                                                                                                                                                                                                  | Size                                     | Make                                                       | Balance    |
|                                                                            | R/H Front Tyre                                                                                                                                                                                                                                   |                                          |                                                            | mm         |
|                                                                            | L/H Front Tyre                                                                                                                                                                                                                                   |                                          |                                                            | mm         |
|                                                                            | R/H Rear Tyre                                                                                                                                                                                                                                    |                                          |                                                            | mm         |
|                                                                            | L/H Rear Tyre                                                                                                                                                                                                                                    |                                          |                                                            | mm         |
| <b>4. Description of Damages</b>                                           |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
| <b>5. General Information</b>                                              |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            | Accident Date                                                                                                                                                                                                                                    | 17/09/2021                               | Inspection Date                                            | 11/10/2021 |
|                                                                            | Survey held at                                                                                                                                                                                                                                   | 3014 Ubi Road 1 #01-322 Singapore 408702 |                                                            |            |
|                                                                            | Repairer                                                                                                                                                                                                                                         | KANEX MOTORSPORTS PTE LTD                |                                                            |            |
| <b>5a. Remarks</b>                                                         |                                                                                                                                                                                                                                                  |                                          |                                                            |            |
|                                                                            | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                          |                                                            |            |