

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs. _____

3

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SHD 6667x

Yr Rogn: _____

9/4, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: _____

Hyundai 140

c.c 1685

Colour: _____

blue

A/C: Insured / Std / NI / NA

Sp. Reading _____

812526

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

17mH1341uMFu067948

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F:

706/60R16

R:

706/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal. _____

5

mm

R/Bal. _____

5

mm

L/Bal. _____

5

mm

L/Bal. _____

5

mm

D.O.A. 3/10/21

D.O.I. 4/10/21

16/5

Survey held at

Comfort

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

rebate: 18047

Date/Time, File Pass to?

☐

: Proff. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Form:

Living Sign / U/C:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end (\$

Survey Fee:

Transportation:

____ S + PS. ____ \$

Pinus

Oliver

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 821R

Vehicle Details

Vehicle No.: SHD6667X
Vehicle to be Exported: No
Intended Deregistration Date: 11 Oct 2021
Vehicle Make: HYUNDAI
Vehicle Model: I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: D4FDFU501135
Chassis No.: KMHLB41UMFU067948
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$20,616.00
Original Registration Date: 09 Apr 2015
First Registration Date: 09 Apr 2015
Transfer Count: 0
Actual ARF Paid: \$13,363.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Apr 2023
PARF Rebate Amount: \$8,685.00

Intended COE Rebate Details

COE Expiry Date: 08 Apr 2023
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$50,177.00
COE Rebate Amount: \$9,362.00
Total Rebate Amount: \$18,047.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Oct 2021

OK