

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21010448/Uvf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	[	Date:	21/10/2021	
			(	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMA 3754D	Veh. Inspected		SJG 1088K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012014/EE	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		12/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL HYBRID (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	RU31266781	Colour		WHITE	
	Odometer	228028 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	215/55 ZR17	WINDFORCE		6 mm	
	L/H Front Tyre	215/55 ZR17	WINDFORCE		6 mm	
	R/H Rear Tyre	215/55 ZR17	WINDFORCE		6 mm	
	L/H Rear Tyre	215/55 ZR17	WINDFORCE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/10/2021	Inspection Date	<b>)</b>	12/10/2021	
	Survey held at	TAN LIM MOTOR PTE LTD				
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: