

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM21010450/Tty3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	14/06/2022	
	ATTN: TEO KITTY		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3711X	Veh. Inspected	SJS 6912K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M03JL9	Excess (\$)	0.00	
	Assign From	TEO KITTY	Assign Date	12/10/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	WVWZZZ1KZAW018138	Colour	RED	
	Odometer	75246 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
	L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
	R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
	L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/10/2021	Inspection Date	12/10/2021	
	Survey held at	urvey held at 1 Kaki Bukit Avenue 6 #01-08 Autobay@Kaki Bukit			
	Repairer	TSL AUTO GARAGE			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				