

# N-51 AUTOMOTIVE PTE LTD

**Company & GST Registration No. 200616038C**

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

**SGU 4127 Z**

Your ref:

**SKT 3100 P**

11 October 2021

## **AUTO & GENERAL INSURANCE (S) PTE LTD**

SINGAPORE SHOPPING CENTRE

190 CLEMENCEAU AVENUE #03-01

SINGAPORE 239924

Attn: Motor Claims Department

Dear Sir/Madam,

**NAME OF CLAIMANT : SONG BIN**

**VEHICLE NUMBER : SGU 4127 Z**

**YOUR INSURED VEHICLE NUMBER : SKT 3100 P**

**ACCIDENT ON 08 Oct 2021 ALONG AYE TWDS CITY B4 LOWER DELTA RD EXIT  
AT ABOUT 09:55 HOURS**

We refer to your email/fax dated **11 Oct 2021** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultant Pte Ltd of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

### **N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-18

Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (ELYNN)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....  
**N-51 AUTOMOTIVE PTE LTD**

#### **FOR SURVEYOR:**

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: