C 10 1 107		+	305489355	ENGINEERING			
Date ;			09/10/21	ComfortDetGra Engineering Pte L 59 Loyang Orive Singapore 5066 Fax 6546 8156			
FINAL	LIZAT	ION FORM			Fa	x: 6046 8105	
Tò	: _	: LKK		Fax ;			
Attn :		-	THEVAN	-			
Vehicle Reg No. : SHA7367X			367X			03/10/21	
The s	urvey	and estimates of t	the repairs of the above-me	intioned vehicl	e are as follow	19	
Z							
	The repair job shall bill to:			NTUC		FBN60591	
2.	The finalized amount shall be:						
	(a)	Spare Parts after	er List discount			****	
	(b)	Labour Charges	,				
		Total for Part-B	By-Part Repair Cost				
	(a.)						
	(c.)	Lumpsum Repair Total for Lumpsi	ir (if applicable) um repair cost after Less:				
		Final Lumpsum	n Repair cost	Nation Control	-	\$1,400.00	
3.	Estim	nated normal perio	od for repairs:	w	orking days.		
4.	We s work	shall treat the abo ing days	ove amount as Correct and	I Confirmed if	there is no re	ply from you within 7	
	work	shall treat the abo ing days lk you for your ass			there is no re		
	work	ang days		W		estimates and	
	work	ang days		W	e confirm the e	estimates and	
5.	Than	ang days		W	e confirm the e	estimates and	
5.	Than	ature:		W fin	e confirm the entitle and amount grature:	estimates and	
5.	Than Signa	ature:	istance.	W fin Sig Na	e confirm the entitle and amount grature:	estimates and	
5.	Than Signa	ature: CHIANG	istance.	W fin Sig Na	e confirm the entitle and amount grature:	estimates and	
5.	Than Signa Name Tel Fax	ature:  CHIANG  : 62148314	istance.	W fin Sig Na	e confirm the entitle and amount grature:	estimates and	
5.	Than Signa Name Tel Fax	ature:  CHIANG  62148314  65468156  Use Only	istance.	W fin	re confirm the enalized amount	Theyan	
5.	Than Signa Name Tel Fax	ature : CHIANG : 62148314	istance.	W fin Sig Na Da	e confirm the entitle and amount grature:	estimates and	
5.	Than Signa Name Tel Fax	ature:  CHIANG  62148314  65468156  Use Only	istance.	W fin	re confirm the enalized amount grature:  gnature:  ame :  ate :  Confirm By	Theyan	
5. For Of	Than Signa Name Tel Fax Intal R	ature : CHIANG : 62148314 : 65468156 Use Only Item atte P/Day ncome Paid	istance.	W fin	re confirm the enalized amount grature:  gnature:  ame :  ate :  Confirm By	Theyan	
5. For Of	Than Signa Name Tel Fax fficial	ature:  CHIANG  : 62148314  : 65468156  Use Only  Item  ate P/Day  ncome Paid	Amount	W fin	re confirm the enalized amount grature:  gnature:  ame :  ate :  Confirm By	Theyan	
5. For Of 1. Rei 2. Los 3. Sui 4. LT/	Than Signa Name Tel Fax fficial  Intal R Invey F A Seai	ature : CHIANG : 62148314 : 65468156 Use Only Item atte P/Day ncome Paid	4 Amount	Document Attached Yes or No YES N	re confirm the enalized amount grature:  gnature:  ame :  ate :  Confirm By	Theyan	

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO

**SHA7367X** 

MAKE

24.07.2019

03/10/21

MODEL

IONIQ G2

CHIANG/NTUC

MODEL	IONIQ G2		1 ,					
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	1/1/4			
	1 REAR BUMPER			\$459.40	1			
	1 REAR BUMPER CENTRE MOULDING			\$451.25	1			
	1 REAR BUMPER REINFORCEMENT				√svc			
	1 REAR BUMPER STAY LH /RH		\$138.10	\$276.20)	1			
	10 REAR BUMPER CLIPS		\$2.20	\$22.00				
	2 BUMPER LICENCE LAMP LH/RH		\$85.30	\$170.60				
	1 BUMPER FOG LAMP			\$201.50				
	1 BBOTLID H EMBLEM		NN	\$38.00				
	2 REAR BUMPER REFLECTOR LH/RH		\$41.45	\$82.90	P			
	2 REAR BUMPER SIDE BRACKET LH/RH		\$55.80	\$111.60	POSS			
				\$2,208.25				
	20.00%			\$441.65				
	DISCOUNTED TOTAL			\$1,766.60				
					tu 1C.			
	2 REAR FENDER ADVERTISEMENT LH/RH		\$100.00	\$200.00 <i>/</i> \$55.00	Me C			
	1 REAR NUMBER PLATE W/HOLDER		-	\$55.00	300			
	1 REAR BUMPER MAT			\$50.00				
	1 REAR REVERSE SENSOR			\$180.00	MAX 40			
				\$485.00				
	Labour Charge				7/0			
	Panel Beating			\$700.00				
	Spray Painting Charge			\$300.00				
	Tuff Kote			\$60.00				
	ChecK Wiring and lighting			\$60.00	•			
	Remove/Refix reverse sensor			\$60.00	30			
	TOTAL LABOUR			\$1,180.00				
	ESTIMATE TOTAL			\$3,431.60				
	`							
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will								
be prepared after the vehicle is surveyed by a motor surveyed by a								
	— I Inc	r Renaller ()	i merionowinu.	1				

Theyan @ Lithauto -low 82235769 4/6/2/ 1600 LIS after repair photos wp 2dags the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: