

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807		Ref: CS/MSG21010470/Buf3 Date: 12/10/2021 Code: MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	YM 1111S	<b>Veh. Inspected</b>	SKR 9305L
<b>Policy No.</b>	30001776102	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	263816	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MERIMEN (KATHERINE WONG)	<b>Assign Date</b>	12/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b>	09/10/2021	<b>Inspection Date</b>	13/10/2021
<b>Survey held at</b>	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			