

150000

CASE OWNER:

CC 4 / AXA1700

8465, 15/03/17

LKK:

IDAC:

Surveyor:

ywk

DOI:

3/5/17

ASSIGNMENT

3

Date / Time:

28/04/2017

Registered in Merimen:

28/04/2017

Pre-assign / CCU / FTE

SGA 7842C

YIM ANN TONG

97538119

28/4/2017

Claim No.:

CO431633

Policy No.:

GA040353

Make / Model:

C-OPIRA-1.6

Place of Accident:

JUNCTION OF BINTAI PARK & DUNEAD RD

Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SK28790H

INSRS:

WSP:

Tel:

Liability:

RMKS:

Supreme

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:





INSRS:

WSP:

Tel:

Liability:

RMKS:

If NO, Driver Name / Age :		OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO	
Driver Tel No. :		(V/L: YES / NO)	Insured Liability : % Final ? Yes / No
SK28790H			
	INSRS: WSP: Supreme Tel : Liability : RMKS:		INSRS: WSP: Tel : Liability : RMKS:
			
Date/ Time			
6th Jan		SK28790H - X ; 66A7842C - X	
14/12/18		Call OI No response	
15/3/19		Call OI No response	
16/3/19		Call OI No response letter sent to OI with addendum.	
19-03-19		TO EXPEDITE, LIABILITY IS DONE.	
09-10-19		URGE TP W/SHOP TO SUBMIT LOD IN ORDER TO CONSIDER SETTLEMENT.	
9/10		10 days notice send TP.	
20/10		TUE call to Steve to find out	
9/11		TO CHECK TO STEVE ON THE NUMBER OF REPAIR DAYS	
6/11		Re call to TP (uploading LOD)	
4/13		No further progression. Self approval from DCA to submit WP.	
10/13		Submit WP. File back OI to close	

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐

Call ☐

Payee 1:

\$S

Name 1:

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

8465/Syaz -

ASSIGNMENT

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop No. _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

Client's Record _____

Make of Veh. _____

Policy Condition _____

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value _____

CAC Accident Report _____ Consistent? Yes or No _____

G.A. FR Seen _____ Consistent? Yes or No _____

Est. Repairs: 4.8 days Rec. Yes or No _____

Lim Sum: 30 % 3 Val: Yes or No _____

CA / REV / REP. / 24 HRS

Date _____ Person Contacted _____

Vehicle: IN / OUT _____

SKZ 3990 H. 11/4/2008

Veh No. 30431947 Yr Reg. _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Albis cc: 1598

Colour: Silver A.C. Insured / Std / Nil / NA

Sp Reading: 184930 T. Radio: Insured / Std / Nil / NA

Eng No. _____

C No: MK053ER1E 106101618

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or _____

Brake: In Order / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16 Riviera

R: 11 Radar

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R.Bal. 6 mm R.Bal. 4 mm

L.Bal. 6 mm L.Bal. 4 mm

D.O.A. 25/4/2017 D.O.I. 7/5/2017

Survey held at Supreme Auto.

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Copyright © 2004

— 1999 —

1000

Figure 1

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

1000

Report Format :

Lump Sum / I.B.I.: \$

Add Fee:	<input type="checkbox"/>	Site Insp	\$
	<input type="checkbox"/>	Interview	\$
	<input type="checkbox"/>	Tech Insp	\$
	<input type="checkbox"/>	Weekend	\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA17008465/Sya3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-04-2017		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGA 7842C	Veh. Inspected	SKZ 8790H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/04/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/04/2017	Inspection Date	03/05/2017	
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

EL & ASSOCIATES
c/o 46 Lentor Plain
Singapore 786548

Date: 3-May-17

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: TOYOTA COROLLA ALTIS / SKZ8790H	
1 pc	front door protector / CMT	208.30
1 pc	rear door / 00	1,293.80
1 pc	rear door protector / CVT	175.90
1 pc	rear door regulator gear / DT	369.70
1 pc	rear door regulator motor / X MM	468.90
1 pc	rear shock absorber / X MM	138.50
1 pc	rear bumper / OR	437.20
1 pc	rear bumper side retainer / OR	89.50
1 pc	side kit (left) X R	586.50
	2380.60	
	- 25%	
	1785.45	
	sub-total	3,768.30
	less 25%	942.08
	sub-total	2,826.23
	ally rim s.nett	350.00
	sub-total	3,176.23
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	500 600.00
	To spray painting on affected areas.	600.00
	To transfer door accessories.	50 90.00
	To remove and install rear undercarriage parts to enable repair.	20 80.00
	To replace alloy rim & perform wheel balancing.	50.00
	L/S - 2684.36 P - 1785.45	
	= 2700 M - 350	
	L - 1220	
	3355.45	
	total	4,596.23

4 days



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

19 MARCH 2018

YIM ANN TONG ✓
APT BLK417 CHOA CHU KANG AVENUE 4 ✓
#08-380 ✓
SINGAPORE 680417 ✓

Dear Sir/Madam,

OUR REF : CC4/AXA17008465/Sma3 ✓
YOUR REF : SGA 7842C ✓
ACCIDENT INVOLVING SGA 7842C AND SKZ 8790H ALONG JUNCTION OF BINJAI ✓
PARK AND DUNEARN RD (T-JUNCTION) ON 25.04.2017 ✓

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SUPREME AUTO SERVICE PTE LTD, acting on behalf of the owner of SKZ 8790H against your motor insurance policy.

Based on the accident report and accident scenario and pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to bevanlim@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at bevanlim@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 9 October 2019 4:27 PM
To: 'chewkeong@supreme.sg'
Subject: YOUR REF: SKZ 8790H (OUR REF: CC4/AXA17008465/Sga3) *** ACCIDENT INVOLVING SGA 7842C & SKZ 8790H ON 25/04/2017 ***

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your ref: SKZ 8790H
Our Ref: CC4/AXA17008465/Sga3

Dear Sir/Madam,

ACCIDENT INVOLVING SGA 7842C & SKZ 8790H ON 25/04/2017

We refer to the above matter.

Kindly check and advise if your client is still interested to pursue with his third-party claim against our principal M/s AXA Insurance Pte Ltd.

Please respond and let us know within 10 days from the date of this e-mail. Otherwise, we shall have no other option but to submit our report to our principal for closure.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."


Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

81 Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Apr 2017		28 Apr 2017 16:40 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YIM, ANN TONG, ID: S2570846F, Tel: +6597538119, Email: MEEITING@INSMART.SG		
Main Claimant:	EL & ASSOCIATES, Co. Reg. No.: 53330796A		
Vehicle Reg. No.:	SKZ8790H	Date of Loss:	25/04/2017 00:00 - :59 [108 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0431633	Policy/Cover Note No.:	GA040353 (Comprehensive)
Vehicle Reg. No. (Insured):	SGA7842C	Policy No. (Claimant):	5078245712-01
		Excess:	S\$0.00
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 64528211		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Kitty Teo - 6880 4602]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 11/05/2017]		
Driver/Custodian (Insured):	YIM, ANN TONG (72 / Male) , NRIC: S2570846F, Tel: +6597538119 Email: MEEITING@INSMART.SG		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AXA_SG (13/03/2020): Re: NOTIFICATION OF MANDATE REQUEST - C0431633/SKZ8790H
- AXA_SG (08/03/2020): Re: NOTIFICATION OF MANDATE REQUEST - C0431633/SKZ8790H
- AXA_SG (26/09/2018): Re: TP settlement - C0431633/GA040353
- AXA_SG (26/11/2017): Re: TP settlement - C0431633/GA040353
- AXA_SG (24/10/2017): TP settlement - C0431633/GA040353

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ8790H (C0431633)
[SGA7842C]
TP
EL & ASSOCIATES
Apr 25 2017 12:00AM
[YIM, ANN TONG]
Supreme Auto Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/04/17 16:39	TP SELECT LKK	<div>Load PDF</div>	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/05/17 17:11	General View	<div>Load JPG</div>	
2	04/05/17 17:11	General View	<div>Load JPG</div>	
3	04/05/17 17:11	General View	<div>Load JPG</div>	
4	04/05/17 17:11	General View	<div>Load JPG</div>	
5	04/05/17 17:11	General View	<div>Load JPG</div>	
6	04/05/17 17:11	General View	<div>Load JPG</div>	
7	04/05/17 17:11	General View	<div>Load JPG</div>	
8	04/05/17 17:11	General View	<div>Load JPG</div>	
9	04/05/17 17:11	General View	<div>Load JPG</div>	
10	04/05/17 17:11	General View	<div>Load JPG</div>	
11	04/05/17 17:11	General View	<div>Load JPG</div>	
12	04/05/17 17:11	General View	<div>Load JPG</div>	
13	04/05/17 17:11	General View	<div>Load JPG</div>	
14	04/05/17 17:11	General View	<div>Load JPG</div>	
15	04/05/17 17:11	General View	<div>Load JPG</div>	
16	04/05/17 17:11	General View	<div>Load JPG</div>	
17	04/05/17 17:11	General View	<div>Load JPG</div>	
18	04/05/17 17:11	General View	<div>Load JPG</div>	
19	04/05/17 17:11	General View	<div>Load JPG</div>	
20	04/05/17 17:11	General View	<div>Load JPG</div>	
21	04/05/17 17:11	General View	<div>Load JPG</div>	
22	04/05/17 17:11	General View	<div>Load JPG</div>	
23	04/05/17 17:11	General View	<div>Load JPG</div>	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/04/17 11:08	CO-CLAIMANT TP & GIA TP_ABS	<div>Load PDF</div>	
2	28/04/17 11:08	EMAIL_ABS	<div>Load PDF</div>	
3	28/04/17 11:08	GIA SGA7842C INSD_ABS	<div>Load PDF</div>	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/18 16:10	LETTER TO OI	<div>Load PDF</div>	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17008465/SGA3Q2

Date: 17/03/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA040353

Claimant

Vehicle No : SKZ8790H

Insured Vehicle No :

SGA7842C

Date of Loss: 25/04/2017

Nature of Claim:

TP

Claim No: C0431633

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ8790H

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 11/04/2008 (Man. Year: 2008)

Chassis No: MR053ZEE106101616

Colour: Silver

Odometer: 184930 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: RIVERA 6 mm

Rear Left Side:

RADAR 6 mm

Front Right Side: RIVERA 6 mm

Rear Right Side:

RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,176.22	2,135.45	1,040.77	32.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	1,220.00	200.00	14.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,596.22	3,355.45	1,240.77	27.00
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	4,596.22	2,700.00	1,896.22	41.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/04/2017

Date Inspected: 03/05/2017 Inspected At:

Supreme Auto Service Pte Ltd (HQ)
176 Sin Ming Drive #02-01, Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g...> 17/3/2020

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ8790H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PROTECTOR (CONSISTENT)	Cut	208.30 FL	*208.30 FL
2	1		*REAR DOOR (CONSISTENT)	Dented	1,293.80 FL	*1,100.00 FL
3	1		*REAR DOOR PROTECTOR (CONSISTENT)	Cut	175.90 FL	*175.90 FL
4	1		*REAR DOOR REGULATOR GEAR (CONSISTENT)	Bent	369.70 FL	*369.70 FL
5	1		*REAR DOOR REGULATOR MOTOR (CONSISTENT)	Not Necessary	468.90 FL	*- FL
6	1		*REAR SHOCK ABSORBER (CONSISTENT)	Not Necessary	138.50 FL	*- FL
7	1		*REAR BUMPER (CONSISTENT)	Broken	437.20 FL	*437.20 FL
8	1		*REAR BUMPER SIDE RETAINER	Broken	89.50 FL	*89.50 FL
9	1		*SIDE KIT (LEFT) (CONSISTENT)	Repair	586.50 FL	*- FL
10	1		*ALLY RIM (CONSISTENT)	Cut	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,118.30	2,730.60
- List Item Discount on L Items 25.00/25.00% (S\$)	942.08	595.15
Total Parts (S\$)	3,176.22	2,135.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	600.00	500.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	600.00	600.00
3	TO TRANSFER DOOR ACCESSORIES	New	90.00	50.00
4	TO REMOVE AND INSTALL REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	80.00	20.00
5	TO REPLACE ALLOY RIM & PERFORM WHEEL BALANCING	New	50.00	50.00
Gross Labour Cost (S\$)			1,420.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >